onsitetruck.hu@gmail.com Phoenix, AZ 85009 2630 West Durango

602-978-2555

Onsite Truck & Equipment Repair.

Parts Inherent Core for DIFFERENTIAL Parts Dirty Core for DIFFERENTIAL Parts Brake Clenaer Parts GEAR OIL Parts DIFFERENTIAL Cause: differential only works with diff lock engaged Complaint: Check and Advise differential gears Item Description Chassis / Suspension / Removed and replaced third member. Cleaned all surface areas. Cleaned passenger side axie shaft splines. Filled 5 gal oil. No miles available, cluster does not work. ~2/5/2020 Correction: P: (515) 444-6936 Thunder trucking Due Date 2/5/2020 2630 West Durango Onsite Truck & Equipment Repair Phoenix, AZ 85009 Remit Payment To Authorizer Customer PO 1.00000 1,00000 \$2,461,29000 \$2,461,29 \$770.00000 \$770.00 \$188,08000 \$770,00000 \$8.14000 Sub Total \$3,578.21 Rate Amount -\$770.00

\$188.08 \$48.84

\$880.00

Unit #

108

Unit: 106 VIN: 4V4ND4JH7YN789529 2000 Volvo VNL

Labor \$880.00

Parts \$2,698.21

Shop Supplies \$150.00

Pre Tax Total \$3,728.21

Arizona State Tax (6.3000% of \$2,848.21) \$179.44

Total \$3,973,16

City of Phoenix Tax Rate (2.3000% of \$2,848.21) \$65.51

Payments & Credits \$3.973.16

Once senice call has been ordered & scheduled there are no carcellations or refunds. After payment has been processed a non-refundable reservation for our service fruck and leotinician has been made. A cuncellation fee will be charged in the amount of 100% of the quoted service fee plus any and alt bank service fees. All sales are final.