

26

Service Invoice

INVOICE NO. R301106282:01
INVOICE DATE 01/23/2020
P.O. NUMBER 304571450
VIN 1FUJGLD59GLGV0313
UNIT GV0313

TRUCK COUNTRY - INDIANAPOLIS 1851 W THOMPSON ROAD INDIANAPOLIS, IN 46217

Phone: (800) 899-1533 FAX: (317) 781-4376

Bill To:

DAIMLER TRUCK FINANCE (INDIANA USE) 246 SCHOOL HOUSE RD PINN = RDTF2 OLD SAYBROOK, CT 06475 Owner:

DAIMLER TRUCK FINANCE (INDIANA USE) 246 SCHOOL HOUSE RD PINN = RDTF2 OLD SAYBROOK, CT 06475

WK PHONE: (630)235-8402

181697 472906S0322124 CUST# S4712 **ENG COLOR** WHT 1/16/20 400264 **ADVISOR SCHED** UNTID EVO MILES **FCB** YEAR MAKE MODEL 448051 **INSVC** 5/2/15 **ACCT** 16 FTL

JOB#1 00 SCP GENERAL REPAIR

CONDITION PERFORM INSPECTION ON TRUCK

CAUSE CUSTOMER REQUEST CORRECTION PERFORMED INSPECTION

JOB#1 00 -- PARTS: 0.00 -- LABOR: 175.00 -- MISC: 0.00 -- SUBTOTAL 175.00

HM PHONE:

JOB#3 INFO SCP INFO

CONDITION UNIT DOES NOT HAVE A KEY, WILL NEED TO CUT ONE.

CAUSE NO KEY
CORRECTION CUT A KEY

QTY	ITEM	DESCRIPTION
1	301F/22-77279-000	KEY-DOOR/IGNITION,M2/P3/P2
1	KEY	KEY CHARGE

JOB#3 INFO -- PARTS: 4.68 -- LABOR: 0.00 -- MISC: 5.00 -- SUBTOTAL 9.68

CUSTOMER

INVOICE NO.	R301106282:01
INVOICE DATE	01/23/2020
P.O. NUMBER	304571450
VIN 1FUJG	LD59GLGV0313
UNIT GV0313	3

CUST#	181697	ADVISOR	S4712	ENGINE	472906S0322124	COLOR	WHT	SCHED	1/16/20	UNTID	400264
YEAR	16	MAKE	FTL	MODEL	EVO	MILES	448051	INSVC	5/2/15	ACCT	FCB

JOB#4 01 SCP ENGINE REPAIR CONDITION CHECK AND ADVISE FOR LOW COOLANT

CAUSE ESPAR HEATER

CORRECTION BROUGHT UNIT IN AND FOUND COOLANT IS LOW. ADDED 1 GAL ANTIFREEZE. DO NOT SEE ANY

RUNNING LEAKS. PUT PRESSURE ON SYSTEM AND WILL LOOK INTO LATER. AFTER BEING ON

PRESSURE FOR AWHILE FOUND THE ESAPR HEATER IS LEAKING FROM INSIDE DOWN THE PIPES. PUT

IN EST

QTY	ITEM	DESCRIPTION	
	01	ENGINE REPAIR	TECH NO. s89876
	001-003EE	AUX HEATER- PART SMART SYSTEM DIAGNOS	STICTECH NO. S4683
1	301F/22-71938-000	HOSE-FORMED, HEATER RETURN, PHVA	
1	301F/ESP 252325050000	HEATER- WITH EXT FUEL PUMP	
1	301F/ESP 252786600001	HOSE-PLASTIC,FLEW,W/O ENDS,PRE	
2	301F/BRZ 9210H	CLAMP-HOSE,9/16-1 1/16IN, 1/2	
2	301F/BRZ 9208H	CLAMP-HOSE,1/2-29/32IN, 1/2 IN	
1	301F/BRZ 9206H	CLAMP-HOSE,7/16-25/32IN, 1/2 I	
3	301D/OWI 23519396	CLNT, LIFE PRE-MIX 50/50, GAL	
1	301F/06-62384-002	SENDER/SENSOR-FLUID LEVEL,COOL	
4	301B/BT4S-C0	BARB TY CABLE TIE, 15.1"L X .1	
1	301F/TYC DCT110HIR	TIE STRAP	
1	301D/OWI 23519397	CLNT, LIFE 100 PCT. , GAL JUG	
		100"	

JOB#4 01 -- PARTS: 1,091.01 -- LABOR: 655.20 -- MISC: 0.00 -- SUBTOTAL 1,746.21

JOB#5 01 SCP ENGINE REPAIR CONDITION CHECK AND ADVISE FOR LOW OIL

CAUSE NPF

CORRECTION CHECKED OIL LEVEL . OK

QTY ITEM	DESCRIPTION	
01	ENGINE REPAIR	TECH NO. s89876

JOB#5 01 -- PARTS: 0.00 -- LABOR: 0.00 -- MISC: 0.00 -- SUBTOTAL 0.00

CUSTOMER

Page 2 of 4

INVOICE NO.	R301106282:01
INVOICE DATE	01/23/2020
P.O. NUMBER	304571450
VIN 1FUJGL	_D59GLGV0313
UNIT GV0313	}

CUST#	181697	ADVISOR	S4712	ENGINE	472906S0322124	COLOR	WHT	SCHED	1/16/20	UNTID	400264
YEAR	16	MAKE	FTL	MODEL	EVO	MILES	448051	INSVC	5/2/15	ACCT	FCB

JOB#6 01 SCP ENGINE REPAIR

CONDITION CHECK AND ADVISE FOR CEL ON

CAUSE DPF FILTE4RS PLUGGED

CORRECTION HAS ACTIVE CODE 3720/15 ASH REQUST. PRINTED OUT REPORT SHOWING 100% ON DPF FILTERS.

QUOTED PARTS FOR NEW DPF FILTER REPLACEMENT

QTY	ITEM	DESCRIPTION	
	01	ENGINE REPAIR	TECH NO. s89876
	246-6171E	ATS - DPF FILTERS R&R (ONE BOX ATS)	TECH NO. S89876
	246-6260E	ATS - REGENERATION OF ATD (PARKED) REGEN	TECH NO. S89876
2	301F/DDE RA0014903492	PT FLTR KIT 13	
2	301F/DDE A6809950202	CLAMP	
10	301F/DDE A0049941645	NUT SPRING	
10	301F/DDE N910105006002	BOLT HXHDFLG	
2	301B/BD1542	BD MPS MULTI-PURPOSE SOLVENT 2	
1	301F/DDE A6805401417	TEMP SENSOR	
2	301F/BRZ 62080H	STD CLAMP	
1	301B/BD3019	CUT OFF WHL, GRADE R/S, 3 X 1/	
(2)	301F/DDE RA0014903492-CORI	EPT FLTR KIT 13	
2	301F/DDE RA0014903492-CORI	EPT FLTR KIT 13	
	С	CORE TAG # 636536 RA0014903492 X2	

JOB#6 01 -- PARTS: 1,450.94 -- LABOR: 717.60 -- MISC: 0.00 -- SUBTOTAL 2,168.54

JOB#7 13 SCP AIR COMPRESSOR

CONDITION CHECK AND ADVISE FOR AIR LEAK

CAUSE DRAIN VALVE

CORRECTION BUILT UP AIR PRESSURE AND LOOKED FOR A LEAK . FOUND SITTER VALVE ON FRONT LEFT BACK

TANK IS LEAKING-PUT IN REQUEST

QTY	ITEM	DESCRIPTION	
	13	AIR COMPRESSOR	TECH NO. s89876
	013-3010A	GEN TIME QUICK RELEASE VALVE - AIR BRAK R	E TECH NO. S89876
1	301F/A12-22111-000	DRAIN VALVE-AIR TANK, W/ CABLE	

JOB#7 13 -- PARTS: 32.56 -- LABOR: 140.40 -- MISC: 0.00 -- SUBTOTAL 172.96

INVOICE REPRINT

CUSTOMER

Page 3 of 4

INVOICE NO.	R301106282:01
INVOICE DATE	01/23/2020
P.O. NUMBER	304571450
VIN 1FUJGL	_D59GLGV0313
UNIT GV0313	

CUST#	181697	ADVISOR	S4712	ENGINE	472906S0322124	COLOR	WHT	SCHED	1/16/20	UNTID	400264
YEAR	16	MAKE	FTL	MODEL	EVO	MILES	448051	INSVC	5/2/15	ACCT	FCB

SALES TAX EXEMPTION CERTIFICAT certify that this transaction is exempt freurchaser is a common contract carrier exclusively as such carrier.		
Authority Number: Purchaser is engaged in the business o		
Resale Number:		_
am authorized to execute this Certifica	te and claim this exception.	
Business Name	Authorized Signature	
Business Address	Date	

DISCLAIMER OF WARRANTIES
ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE
MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY
EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR
MPLIED INCLUDING ANY MPLIED WARRANTY OF MERCHANTABILITY
OR FITNESS FOR A PARTICULAR PURPOSE, AND TRUCK COUNTRY
OF INDIAMS AND ANY OF A PARTICULAR PURPOSE, AND TRUCK COUNTRY
OF INDIAMS AND ANY OF A PARTICULAR PURPOSE, AND TRUCK COUNTRY
PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH
THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE
GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE
REQUIREMENTS OF SECTIONS A, AND 12 OF THE FAIR LABOR
STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND
ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION
ISSUED UNDER SECTION 11 THEREOF. TRUCK COUNTRY DOES
EXPRESS A LIMITED NON-TRANSFERRABLE WARRANTY, TO THE
ORIGINAL PURCHASER, ON TECHNICIAN WORKMANSHIP ISSUES FOR
30 DAYS FROM THE COMPLETION DATE OF THIS REPAIR ORDER. A
FINANCE CHARGE OF ONE AND ONE-HALP PERCENT (1 '9's) PER
MONTH IS APPLIED TO ALL ACCOUNTS 30 DAYS PAST DUE. THIS
EQUIALS AN ANNUAL PERCENTAGE RATE OF EIGHTEEN PERCENT
(18%). DISCLAIMER OF WARRANTIES RECEIVED

Motor vehicle repair practices are regulated by chapter ATCP 132, Wis. Adm. Code, administered by the Bureau of Customer Protection, Wisconsin Dept. of Agriculture, Trade and Consumer Protection, P.O. Box 8911, Madison, Wisconsin 53708-8911.

EXPENCES, INLCUDING ATTORNEY AND COURT COSTS INC BY TRUCK COUNTRY FOR PAYMENT OF THIS INVOICE.

CUSTOMER

-- PAYABLE IN US DOLLAR --Please Remit Payment to: TRUCK COUNTRY OF WISC PO BOX 689707

MISC CHARGES

MISC SUPPLIES

CHICAGO, IL 60695-9707

PARTS

LABOR

SUBLET

TOTAL

TAX

PACKAGES DIAGNOSTIC

Page 4 of 4

5.00

0.00

0.00

0.00

253.23

4,525.62

2,579.19

1,688.20