

R301107564:01 INVOICE NO. INVOICE DATE 02/17/2020 304586000 P.O. NUMBER 1FUJGLD58GLGV0285 VIN UNIT

Service Invoice

DIVISION OF TRUCK COUNTRY

TRUCK COUNTRY - INDIANAPOLIS 1851 W THOMPSON ROAD INDIANAPOLIS, IN 46217 Phone: (800) 899-1533 FAX: (317) 781-4376

Bill To: DAIMLER TRUCK FINANCE (INDIANA USE) 246 SCHOOL HOUSE RD PINN = RDTF2 OLD SAYBROOK, CT 06475

(630)235-8402

WK PHONE:

Owner: DAIMLER TRUCK FINANCE (INDIANA USE) 246 SCHOOL HOUSE RD PINN = RDTF2 OLD SAYBROOK, CT 06475

181697 472906S0313845 CUST# S4978 ENG COLOR WHT 2/11/20 400236 **ADVISOR** SCHED UNTID EVO MILES FCB YEAR MODEL 496082 INSVC 4/3/15 ACCT 16 MAKE FTL CUSTOMER REQUESTS TO JOB#1 CR SCP PERFORM 1 HR DAIMLER TRUCKS FINANCIAL TRUCK INSPECTION. CONDITION INSPECTION CAUSE INSPECTION COMPLETED CORRECTION QTY ITEM DESCRIPTION CR CUSTOMER REQUEST **TECH NO. S4556** JOB#1 CR -- PARTS: 0.00 -- LABOR: 175.00 -- MISC: 0.00 -- SUBTOTAL 175.00 JOB#3 INFO SCP INFO NO KEY, HAVE KEY MADE. CONDITION CAUSE NEEDS A KEY CORRECTION MADE A KEY QTY ITEM DESCRIPTION 1 301F/22-77279-000 KEY-DOOR/IGNITION,M2/P3/P2 1 KEY

KEY CHARGE

JOB#3 INFO -- PARTS: 4.68 -- LABOR: 0.00 -- MISC: 5.00 -- SUBTOTAL 9.68

HM PHONE:

CUSTOMER

Page 1 of 3

PINNACLE CUSTOMER - NO MAIL COPY

Truck Country Cedar Rapids moved to 8415 6th Street SW, Cedar Rapids, IA. Stop in at our new facility.

64

INVOICE NO. R301107564:01 INVOICE DATE 02/17/2020 P.O. NUMBER 304586000 VIN 1FUJGLD58GLGV0285 UNIT

CUST#	181697	ADVISOR	S4978	ENGINE	472906S0313845	COLOR	WHT	SCHED	2/11/20	UNTID	400236
YEAR	16	MAKE	FTL	MODEL	EVO	MILES	496082	INSVC	4/3/15	ACCT	FCB
JOB#4 4	9		SCP EX	HAUST							
CONDITI	ON	REGEN WARI	NING LIGHT S	TAYS ON							
CAUSE		DPF FILTERS									
CORREC	TION	BRING TRUC	K IN SHOP. H	OOK UP C	OMPUTER AND F	RINT CODI	ES. HAS AC	TIVE CODE	E FOR DPF	ZONE 2.	
		BACK UNIT OUTSIDE AND PERFORM REGEN. CODE DID NOT GO INACTIVE AFTER REGEN. DOC INLET									
		PRESSURE M	IAXED OUT A	T 1.8PSI. P	OSSIBLY STUCK	IN FACEPL	UG ROUTI	NE. START	DOC FACE	EPLUG	
		ROUTINE FOI	R 10 MINUTES	. ABORT F	ROUTINE. START	REGEN. RE	EGEN COM	PLETED TH	IS TIME A	ND CODE	
		WENT INACT	IVE. DOC INLE	ET PRESSI	JRE MAXED OUT	AT 2.1 PSI	THIS TIME.	DPF ASH A	ACCUMUL	ATOR IS	
		TO THE END	OF THE DPF L	IFE CYCL	E. LIKELY THAT 1	HE DPFS A	RE CAUSI	NG THE ISS	SUE, BUT C	CANNOT	
		CONFIRM. RE	COMMEND P	ERFORMI	NG ATD CHECKLI	ST, REPLA	CING DPF'S	6, AND PER	FORMING	DOC	
		BLOW-OUT P	ROCEDURE.	THEN RUN	ANOTHER REGE	N TO VERI	FY DOC IN	LET PRESS	URE HAS	COME	
		DOWN. PUT I	N UPTIME RE	QUEST FO	R NEW DPF'S. U	PDATE FOR	REMAN. PA	RK UNIT AT	THIS TIM	E. BRING	
		UNIT IN SHOP. REMOVE RH FAIRING, STEP BRKTS, TRIM COVER, 1-BOX HEAT SHIELDS, AND DPF'S									
		FROM 1-BOX. TAKE DPF'S NEXT DOOR AND FLOW TEST THEM FOR RESTRICTION. FOUND BOTH FILTERS									
		AT 3.6". GET ⁻	TOOLING FOR	R DOC BLO	W-OUT. REMOVE	E INLET TO	1-BOX AND	D PERFORM	I THE DOC)	
		BLOW-OUT PROCEDURE. CLEAN GASKET MATERIAL OFF INLET TO 1-BOX AND DPF MOUNTING									
		SURFACES. INSTALL NEW DPF'S IN 1-BOX. DPF SERIAL #'S- 12400015046620, 12400015090572 .									
		REINSTALL IN	NLET TO 1-BO	X WITH NE	EW CLAMP AND O	GASKET. PE	RFORM AT	TD CHECKL	IST. FOUN	ID DELTA	
		P PORTS SLI	GHTLY PLUGO	GED WITH	SOOT AND HIGH	IDLE TIME	IS THE PFI	P. REINSTA	LL THE 1-E	BOX HEAT	Г
		SHIELDS WIT	H NEW U-NUT	S AND BC	LTS. REINSTALL	TRIM PIEC	E AND STE	P BRKTS. L	JPDATE D	PF	
		SERIAL NUME	BERS IN DIAG	NOSTICLI	NK TO RESET TH	E ASH ACC	UMULATO	R. BACK UN	IT OUTSIE	DE AND	
		PERFORM RE	EGEN. DOC IN	LET PRES	SURE REDUCED	TO NORMA	AL. NO LEA	KS AT THIS	TIME. RE	INSTALL	
		FAIRING. TUF	RN IN OLD DPI	-'S FOR C	ORES.						
ΟΤΥ	/ ITEM			ESCRIPTI	NN						

QTY	ITEM	DESCRIPTION					
	49	CHECK AND ADVISE	TECH NO. s1432				
	DPF	R & R DPF FILTER(S) WITH REMANS	TECH NO. S1432				
	01	PERFORM DOC BLOW OUT	TECH NO. S1432				
	01	ATD CHECK LIST	TECH NO. S1432				
2	301F/DDE RA0014903492	PT FLTR KIT 13					
2	301F/DDE A6809950202	CLAMP					
1	301B/C21537	3M UTILITY DISC, T1, R0LOC, 3"					
12	301B/BT4S-C0	BARB TY CABLE TIE, 15.1"L X .1					
1	301F/TCX AMS013	GASKET-5 INCH SPHERICAL W/TABS					
1	301F/TCX T130158342AB2	CLAMP-EXHAUST 5 INCH SPHERICAL					
1	301F/DDE A6805402117	TEMP SENSOR					
(2)	301F/DDE RA0014903492-CORE PT FLTR KIT 13						
2	301F/DDE RA0014903492-CORE PT FLTR KIT 13						
	С	CORE TAG # 633318 DPF A0014903492 T					
	С	CORE TAG # 633319 DPF A0014903492 T					
	JOB#4 49 PARTS: 1,465.43 LABOR: 1,716.00 MISC: 0.00 SUBTOTAL 3,181.43						

CUSTOMER

Page 2 of 3

PINNACLE CUSTOMER - NO MAIL COPY

Truck Country Cedar Rapids moved to 8415 6th Street SW, Cedar Rapids, IA. Stop in at our new facility.



INVOICE NO. R301107564:01 INVOICE DATE 02/17/2020 P.O. NUMBER 304586000 VIN 1FUJGLD58GLGV0285 UNIT

CUST#	181697	ADVISOR	S4978	ENGINE	472906S0313845	COLOR	WHT	SCHED	2/11/20	UNTID	400236
YEAR	16	MAKE	FTL	MODEL	EVO	MILES	496082	INSVC	4/3/15	ACCT	FCB
INVOICE REPRINT											

	CUSTOMER	Page 3 of 3		
Motor vehicle repair practices are regulated by chapter ATCP 132, Wis. Adm. Code, administered by the Bureau of Customer Protection, Wisconsin Dept. of Agriculture, Trade and Consumer Protection, P.O. Box 8911, Madison, Wisconsin 53708-8911.	SIGNATURE BY THE CUSTOMER OR CUSTOMER REPRESENTATIVE CONSTITUTES AGREEMENT TO PAY REASONABLE LEGAL EXPENCES, INLCUDING ATTORNEY AND COURT COSTS INCURRED BY TRUCK COUNTRY FOR PAYMENT OF THIS INVOICE.	Please Remit Paymen TRUCK COUNTRY OF PO BOX 689707 CHICAGO, IL 60695-9	WISC	
		PAYABLE IN US DOLLAR		
	RECEIVED BY:	TOTAL	3,649.76	
Business Address Date	30 DAYS FROM THE COMPLETION DATE OF THIS REPAIR ORDER. A FINANCE CHARGE OF ONE AND ONE-HALF PERCENT (1 % %) PER MONTH IS APPLIED TO ALL ACCOUNTS 30 DAYS PAST DUE. THIS EQUALS AN ANNUAL PERCENTAGE RATE OF EIGHTEEN PERCENT (18%).	TAX	0.00	
Business Name Authorized Signature	ISSUED UNDER SECTION 14 THEREOF. TRUCK COUNTRY DOES EXPRESS A LIMITED NON-TRANSFERRABLE WARRANTY, TO THE ORIGINAL PURCHASER, ON TECHNICIAN WORKMANSHIP ISSUES FOR	MISC SUPPLIES	283.65	
I am authorized to execute this Certificate and claim this exception.	GODIS WERE PRODUCED IN COMPLANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION	DIAGNOSTIC SUBLET	0.00 0.00	
Resale Number:	PERSON TO ASSUME FOR IT ANY LUBILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE	PACKAGES	1,001.00	
Authority Number: Purchaser is engaged in the business of and items will be used for resale.	IMPLIED INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND TRUCK COUNTRY OF Indiana NEITHER ASSUMES NOR AUTHORIZES ANY OTHER	LABOR	1,891.00	
Purchaser is a common contract carrier who will use items purchased or serviced exclusively as such carrier.	MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR	PARTS	1.470.11	
SALES TAX EXEMPTION CERTIFICATE I certify that this transaction is exempt from the Indiana Sales Tax because:	DISCLAIMER OF WARRANTIES ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE	MISC CHARGES	5.00	

PINNACLE CUSTOMER - NO MAIL COPY

Truck Country Cedar Rapids moved to 8415 6th Street SW, Cedar Rapids, IA. Stop in at our new facility.