

REMIT TO: Michigan CAT Dept.# 77576 P.O. BOX 77000

Detroit, Michigan 48277-0576

CUSTOMER INVOICE

Service Dept. 25000 Novi Rd. Novi, Michigan 48375

Reliable Carriers Inc

41555 Koppernick Rd

SOLD TO

Ph 248 349 7050 Fax 248 349 7508

SHIP TO

Reliable Carriers Inc Canton, Michigan 48187 OK-tholdings in

| INVOICE NUMBER | INVOICE DATE | ORDER NUMBER PSD-WO-3344310 | DOCUMENT DATE | CUSTOMER PO NUMBER | | PAGE | |
|---------------------|--------------|-----------------------------|----------------------------|-------------------------|-------|----------|--|
| SD3421582 | 09/09/2013 | | 08/13/2013 | 30598CB | | 1 OF 3 | |
| MAKE CATERPILLAR | MODEL C15 | EQUIPMENT NUMBER 30598 | SERIAL NUMBER 0BXS26118 | METER READING 826088 | PRICE | SHIP VIA | |

All repairs and parts listed were furnished in compliance with the Michigan Motor Vehicle Service and Repair Act. Repairs properly completed and checked by: DAN IZZARD M210820 Michigan repair facility registration number: F104694

oluB

SEG. 1/TROUBLESHOOT/ENGINE

COOLANT LEAK.

REPAIR: BROUGHT INTO SHOP DRIVER STATES THERE IS A COOLANT LEAK. DID DOWNLOAD. REMOVED AIR PIPING; NO COOLANT IN PRE COOLER. PRESSURIZED SYSTEM FOUND NO LEAKS. RAN ENGINE TO TEMP FOUND THAT IT BUILDS MORE THAT 20 PSI, BYPASSED AIR COMPRESSOR, STILL BUILDS OVER 20PSI FAST, NEED TO REMOVE CYLINDER HEAD AND INSPECT.

LABOR

2.50

Regular hours

Shop

SEGMENT 1

TOTAL LABOR SEGMENT TOTAL 101.00

252.50

252.50

252.50

SEG. 2 / RECONDITION / ENGINE

REPAIR: DRAINED COOLANT. REMOVED TOP DECK PLATE ON TRUCK TO GET HEAD OFF TRUCK. REMOVED CYLINDER HEAD., CLEANED TOPS OF PISTONS, ALL OK .CHECKED LINER WEAR HAS .004 - .006 WEAR AND HEAD HAS INTERNAL CRACK, NEED TO RECONDITION ENGINE WITH PLATINUM OVERHAUL) REMOVED AND REPLACED CYLINDER PACKS. ROD BEARINGS, MAIN BEARINGS, CYLINDER HEAD, INJECTORS, WATER PUMP, AND OIL PUMP. FOUND OIL COOLER COMING APART. REPLACED OIL COOLER. FOUND MAIN WIRING HARNESS, AND INJECTOR HARNESS' ARE FRAYED AND COMING APART. CUSTOMER WANTED VVA SOLENOIDS CHANGED. REPLACED MAIN AND INJECTOR HARNESSES AND VVA SOLENOID. ASSEMBLED ENGINE. TORQUED AND ADJUSTED ALL, FILLED WITH FLUIDS, RAN TO TEMP, RAN ON DYNO. MAKES 420HP, ABOVE SPEC. FINSHED PAINTING ENGINE AND PULL OFF DYNO. CHECKED OVER AND PARKED.

| PARTS 1 1.00 15.00 3 1 1 7 1 | 10R9925 1656170 2470266 3196059 3393768 9N3368 2913866 | KIT ENG OVER Core charge Full core credit PLUG HOSE KIT-DIAPHRAG COOLANT DEAC FILTER A SER OIL-DEO(ULS) | WO#23087 PO#21799 4540 |
|--|--|---|------------------------------|
|--|--|---|------------------------------|

SEGMENT 2

SEGMENT TOTAL (FLAT-RATE)

17,880.00



INVOICE DATE

INVOICE NUMBER

ORDER NUMBER

REMIT TO: Michigan CAT Dept.# 77576

CUSTOMER PO NUMBER

P.O. BOX 77000

Detroit, Michigan 48277-0576

PAGE

| SD3421582 | The state of the s | PSD-WO-3344310 | 0011010110 | 598CB | 2 OF 3 |
|------------|--|-----------------------|--|--|-----------|
| QUANTITY | ITEM | is DE | SCRIPTION | UNIT PRICE | EXTENSION |
| CG. 3/ITEN | IS NOT INCL. FLAT R | RATE / ENGINE | | | |
| | | | . REMOVED AND REPLACED E | NGINE HARNESS. | |
| | HIV EINGINE HAMINEOU | TIAD DICORDI, MILLOND | A A COLUMN TO THE REAL PROPERTY OF THE PARTY | The second secon | |
| ARTS | 2017201 | HOSE AS | | 39.03 | 39.03 |
| 1 | 3217384 | HOSE AS MAO | | 26.01 | 26.01 |
|] | 2201206 | | | 19.03 | 19.03 |
| 1 | 2769507 | HOSE | | 566.73 | 1,700.19 |
| 3 | 10R3578 | VALVE ACTUA | | 239.67 | 719.01 |
| 3.00 | | Core charge | | -239.67 | -719.01 |
| 3.00 | | Full core credit | | 882.11 | 882.11 |
| 1 | 10R2112 | CORE AS OIL | | 258.37 | 258.37 |
| 1.00 | | Core charge | | -258.37 | -258.37 |
| 1.00 | | Full core credit | | | 20.08 |
| 2 | 1090077 | SEAL ORING | | 10.04 | 0.60 |
| 2 | 0S1594 | CAP SCREW | | 0.30 | 1.80 |
| 4 | 0S1588 | BOLT | | 0.45 5.07 | 5.07 |
| 1 | 2388253 | HOSE | | | |
| 2 | 1616963 | CLAMP | | 0.32 | 0.64 |
| 1 | 2470055 | HOSE | | 44.38 | 44.38 |
| 2 | 1135304 | SEAL | | 16.18 | 32.36 |
| 4 | 0S1588 | BOLT | | 0,45 | 1.80 |
| 8 | 5M2894 | WASHER | | 0.28 | 2.24 |
| 4 | 3B1915 | BOLT | | 0.49 | 1.96 |
| 1 | 2554533 | HARNESS AS | | 180.40 | 180.40 |
| 1 | 2554534 | HARNESS AS | | 159.19 | 159.19 |
| 1 | 2568753 | FILTER AS SE | | 20.54 | 20.54 |
| 25 | 5P0743 | CM-HOSE STK | | 0.30 | 7.50 |
| 18 | 2431159 | FASTENER | | 7.11 | 127.98 |
| 1 | 2413150 | HARNESS AS | | 592.57 | 592.57 |
| ABOR | | | | | |
| 1.50 | Regular hours | Shop | | 101.00 | 151.50 |
| | | SEGMENT 3 | TOTAL PARTS | | 3,865.48 |
| | | OMOINTHIA O | | | 151.50 |
| | | | TOTAL LABOR | | |
| | | | SEGMENT TOTAL | | 4,016.98 |
| ana atani | BUT BYPENDED W. | DDINTY | | | |
| | D / VA EXTENDED WA | | en commo lo Movembro della la | TTED MILEACE | |
| | | 36 MONTH OPT COVE | ERAGE TO 48 MONTHS, UNLIM | HED MILEAGE. | |
| MISCELLAN | | | | 0.000.00 | 0.000.0 |
| 1 | OPT (REP-L) covera | | FREE 36 MONTH OPT C | 3,260.00 | 3,260.00 |
| 1 | Truck service promo |) | OPT 3 YEAR COVERAGE | -2,470.00 | -2,470.0 |
| | | SEGMENT 4 | TOTAL MISC. CHARGES | | 790.00 |
| | | OLOMEITI 4 | SEGMENT TOTAL | | 790.0 |
| | | | | | |
| | SUBTOTAL | L BEFORE TAXES | 3 | | 22,939.4 |
| | AND AND 10 AND 1 AND 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 | | | | |
| | | Env | ironmental charges | | 18.1 |

DOCUMENT DATE



REMIT TO: Michigan CAT

Dept.# 77576 P.O. BOX 77000

Detroit, Michigan 48277-0576

| INVOICE NUMBER | INVOICE DATE | ORDER NUMBER PSD-WO-3344310 | DOCUMENT DATE 08/13/2013 | CUSTOMER PO NUMBER 30598CB | PAGE 3 OF 3 |
|-----------------------|--------------|-----------------------------|-----------------------------|-------------------------------|----------------|
| SD3421582 QUANTITY | ITEM | | DESCRIPTION | UNIT PRICE | EXTENSION |

PAYMENT TERMS

Pay in full 30 days after invoice date. A monthly Finance Charge of 1.75% (21% APR) will be added on all past due amounts.

For payment questions about this invoice please contact Denise Wethington
Fax 1-866-473-4921

Voice 248-349-4800 Ext. 1486

Email denise.wethington@michiganeat.com

| CREDIT AMOUNT DO NOT PAY | 0.00 |
|-----------------------------|-----------|
| PAY THIS AMOUNT | 22,957.66 |

CATERPILLAR®

OVERHAUL PROTECTION ON-HIGHWAY VEHICLE ENGINES

Overhaul Protection For Cat® On-Highway Vehicle Engines
Registration Certificate For Overhauls Performed Worldwide (Excludes Colombia and Venezuela)

Effective Date: July 1, 2013

| | | | ate. July 1, 2010 | IONE.724 | 152 6677 | | | |
|---|-------------------------|---|---|-----------------------------|--|---|--|--|
| CUSTOMER NAME: RELI | ABLE CARRIER | S, INC | | HONE:734-4 | | | | |
| ADDRESS:41555 KOPPE | RNICK ROAD | | | TY:CANTO | | | | |
| STATE / PROVINCE:MI | | POSTAL CODE:48187 COUNTRY:UNITED STATES | | | | | | |
| CAT® DEALER: MICHIGAN | CAT | | DEA | LER CODE: _I | B293 | | | |
| ADDRESS: 25000 NOVI RO | DAD | | CIT | Y: NOVI | NAMES OF THE PARTY | particular persons such that or opposite the same (see al.) | | |
| STATE / PROVINCE: MI | | POSTAL CODE: 48375 COUNTRY: UNITED STATES | | | | | | |
| TEPS DEALER: | | | DEA | LER CODE: | | | | |
| | | | CITY | | The state of the s | | | |
| STATE / PROVINCE: | | POSTAL | CODE: | CO | UNTRY: | | | |
| PROVIDER: See Section XIV. | | | | | | | | |
| REGISTRATION DETAIL | Engine Serial No. : | BXS26118 | Engine Sales Mo | | | epower: 475 | | |
| New Registration | Application : ON I | HIGHWAY TRUCK | Engine Overhaul | /OPT Start Da | te : Aug 30, 2013 | | | |
| Delayed Coverage Start | Start ECM Mi/Kms | : 826088 | Start Odometer | Mi/Kms : | 820561 | 20561 | | |
| Transfer of Ownership | Replacement Date | : | ECM Mi/Kms : | 0 | dometer Mi/Kms | : | | |
| Replacement Engine | Transfer Date : | | | dometer Mi/Kms : | | | | |
| Upgrade of Coverage | | Veh. Model : VIN : | | | | | | |
| | | COVERAGE O | PTIONS AND TERMS | | | a me igr | | |
| Heavy Duty Coverage Month | s Miles/Kms | Price | Medium Duty Coverage | Months | Miles/Kms | Price | | |
| OPT 48 | UNLIMITED | \$790.00 | OPT | | | | | |
| Towing (U.S.A. & Canada Only) | | | Towing (U.S.A. & Canada Only) | | | * | | |
| IMPORTANT: Overhaul Workshot Time and Mileage Limitations: | | | | | ate!! : U.S.A. \$ | \$0 | | |
| EXTENDED COVERA | <u>11</u> | Coverage Fee | (from above): U.S.D.\$ | \$ 790 | | ity: amount we will gle claim will be | | |
| This contract provides only the with a months and miles/kms | term indicated | | Late Fee: U.S.D. \$ | | the reasonable | cost to repair or | | |
| above. Coverage options liste | ed above may not | | Tax: U.S.D. \$ | replace the covered vehicle | | | | |
| be available for all engine mo applications. Dealer - Refer to lists for currently available o and applications . | published price | Total Coverage Fee: U.S.D. \$ \$790 | | | engine, not to exceed Caterpillar's list price for equivalent replacement engine. | | | |
| I hereby certify that I have read an checked above and as specified wi indicated on the bottom of this Re | thin the additional nun | and conditions of pages | I hereby certify that the engine coverage as specified on this Re Dealer's responsibilities as spec | egistration Certif | ficate and have read | and understand the | | |
| C Beauly | ت | Sep 9, 2013 | Chwell | | Sep 9, 2013 | | | |
| Customer Signature | ck | Date | Authorized Dealer Represe | ntative | 8 | Date | | |

CATERPILLAR

OVERHAUL PROTECTION ON-HIGHWAY VEHICLE ENGINES

OPERATING WORLDWIDE (Excludes Colombia and Venezuela)

Overhaul Certification Worksheet - This is NOT The Registration Form **Program Effective Date: July 1, 2013**

| Overhaul Date: | Aug 19, 2013 | Overhauli | ng Dealer: | | MICHIGAN CAT | Overhau | ıling Dealer | Code: | B293 | |
|---|-----------------------------|------------------------|-----------------|-------------|---|---|-----------------|-----------------------------|-----------------------|------------|
| Owner Name: | | CARRIERS | 5200 | Address | : 41555 KOPPERNICK RD, CANTON, N | 11 48187 | | | | |
| Vehicle Year / Make / M | | | - | | Engine Sales Model | | ngine S/N: | BX526118 | | |
| HP: 475 ECM Start M | | 826,088 | Odometer | Start Mil | les/Kms: 820,561 Total | Fuel (Gallons/Lit | ers): | 177,7 | 16 | |
| REQUIRED ACTION | | | | LETED | OPTIONAL REPLACEMENT C | OMPONENTS | * Replaced | Exceptio | n | · |
| Download ECM and F | | its and Lifetime Tota | als > | Yes | Front Cover Gasket | | \subset | (| | |
| Check SIMS and perfo | | | [> | | Turbocharger(s)** / Seals / Gaske | ets | \subset | • | | |
| Engines must comple REQUIRED REPLACE | | | [> | Yes | Water Pump / Seals / Gaskets | | (| \subset | | |
| Thermostat | JEMENI COMI | ONENIS | | X Yes | | | (| \subset | | |
| Spacer Plate Gasket | | | | Yes | Unit Injectors*** | | C | 6 | | |
| Rod, Main & Thrust B | earings | | | × Yes | Air Compressor Variable Valve Actuators (VVAs) | Assembly*** | • | \subset | | |
| Valve Cover Gasket | | | [| Yes | Valiable Valve Actuators (VVVO) | (330)(101) | | | | |
| Oil Filter, Fuel Filters, | and Cooling Syst | em Conditioner | [: | × Yes | ADDITIONAL COMPONENTS | | INSPECT Yes | ED Repl | aced E | xception |
| Cylinder Packs (Requ | | | | Yes | Pre-Cooler (turbocharger) + | | \times | (| | |
| Piston Group Wrist Pi | | Rings (Where Appl | | Yes | Pre-Cooler Mounting Bracket (tur | hocharger) ++ | \boxtimes | (| - | Č |
| Piston Body Assembl | | | Γ | Yes | Coolant Diverter Valve or Assemb | | \times | | | |
| Exhaust Manifold Stu | | | [| ∠ Yes | Engine Oil Rail (EOR) Valve | | \times | - | | (' |
| Cylinder Head Assem | | | - | Yes | | NOTE; | | | | |
| Injector Sleeve Seal (| | Trinjector Siceves | _ | × Yes | *Optional Replacement Component | s are covered onl | y if replaced | with new or | Caterpil | lar |
| • | - | Park (a) | L | Yes | Remanufactured components at tirr ** If the engine has two turbocharge | er(s), both must be | e replaced to | qualify for o | ptional | |
| Connecting Rod Asse | | licable) | L | | coverage. *** Electronic Unit Injectors and Var | iable Valve Actua | itors (VVAs) | must be repl | aced as | a set |
| Fuel Nozzles (Where | | | l I | Yes | to qualify for optional coverage. + Pre-Cooler is covered only if inspe | | | | | |
| Cam Follower Spring | | |] | Yes | is of the latest design at the time of | the overhaul. | | | | |
| O Ring Seals (between | | 5 10 12 15 | 6 Only) | Yes | ++ This component must be of the I confirm the latest design or replace | atest design to que this component a | alify for cov | erage. Deale the overhau | ers must I to rece | ive |
| Cylinder Head Bolts of Variable Valve Actual | | | nnlicable c | Yes | coverage under the program. | Mus (2011) (1 1 1 1 1 1 | | | | |
| and NOT the lates | | ang Stads (where a | L | × Yes | | | | | | |
| Components listed in this | s section are cove | red only if they pass | inspection | are renair | TED COMPONENTS ed or replaced during the overhaul. Pa | rts not replaced m | nust be withi | n the specific | ations s | et forth |
| in the Service Manual or | applicable Guide | ine for Reusable Pa | irts. If a com- | ponent fai | is the inspection and is not repaired or | replaced it will no | t be covered | d under this p | orogram | In this |
| case the Exception box | snould be marked INSPECT | | riponents as | denined | by applicable service guide must be rep | INSPECTED | | W 100 | | |
| 8 | Yes | | Exceptions | | | Yes | Repaired | Replaced | Excepti | ons |
| Thermostat Housing | \times | C | \subset | | Cylinder Head Bolts | \times | | (| (| |
| Spacer Plate / Spacer E | | \mathcal{C} | \subset | E | Exhaust Manifold | \boxtimes | | (| (| |
| Camshaft | \times | C | | \ | /alve Cover & Base | \boxtimes | | (| (| |
| Camshaft Follower / Lift | ter X | C | C | V | Vater Pump Housing | \boxtimes | | (| (| |
| Vibration Damper | \times | \subset | \subset | F | Tywheel Housing | \times | | (' | (| |
| Crankshaft | X | | | F | ront Housing | \times | | | | |
| Oil Pump | \Box | • | $\overline{}$ | * | Cylinder Block / Deck / Counter Bore | \times | $\overline{}$ | C | (| |
| Front Covers and Plate | | C | \subset | F | Piston Cooling Spray Jets | \times | | $\overline{}$ | (| |
| Oil Cooler Housing | | C | (| 1 | Dil Pan | \boxtimes | | | (| |
| Rocker Arm Assembly | | C | (| F | reeze Plugs | \boxtimes | | (| (| |
| Intake Manifold | | C | \mathcal{C} | | Main Bearing Cap Bolts | × | | $\overline{}$ | | |
| SOUND CONTROL OF TOXABLE CONTROL | rhaul if the cylinder | block is cracked or is | or has been v | velded / re | paired, the block must be replaced or chec | cked as a exception | and is not o | overed under | the prog | ram. |
| The dealer has explained the | nis Overhaul Certifica | tion Worksheet to me | | | I hereby certify that the appropriate Overhau the engine is eligible for Overhaul Protection | I Certification proceed | dure as specifi | ed above has l | been com | pleted and |
| identified during this overha | aul, by this inspection | , nave been corrected. | | | utilized on the repairs listed above. A copy | of the Dealer Work C | order is attach | ed | | |
| 1 horas | chi | Sep ! | 9, 2013 | | tom he de | cele | | Sep 9, 2 | 2013 | |
| Customer Signature | all | Da | te | _ | Dealer Service Manager Signature | | | Date | | |
| | U | | | | Con Cot / TERS Doole | - | | | LE | HT0117-02 |