

5453 - EXCAVATOR E-42-BOBCAT

E42 #7

AG 3413136

10/17/2019

Contract	Repairs	Broken	Repaired	Hours	Qty	Amount	Repair Cost	Contract Info
+ r13054	REPAIRS-INTERNAL	10/16/2019	11/13/2019	672	1	0.00	0.00	SOLD MACHINES
+ r12894	REPAIRS-MAINT	9/26/2019	9/26/2019	1	1	0.00	71.75	Maintenance Required
+ r12424	REPAIRS-INTERNAL	7/22/2019	7/23/2019	29	1	0.00	119.74	NEEDS TOP ROLLER ON PASSENGER SIDE
+ r11416	REPAIRS-SERVICE	3/6/2019	3/6/2019	1	1	0.00	60.10	Service Call for REPLACED BATTERY
+ r11378	REPAIRS-INTERNAL	2/27/2019	2/28/2019	18	1	0.00	0.00	CUSTOMER COMPLAINED ABOUT THE BOOM SWING
+ r11200	REPAIRS-INTERNAL	1/30/2019	1/31/2019	17	1	0.00	76.33	BUCKET CYLINDER LEAKING
+ r11146	REPAIRS-MAINT	1/23/2019	1/23/2019	1	1	0.00	94.99	Maintenance Required
+ r11125	REPAIRS-INTERNAL	1/18/2019	1/18/2019	1	1	0.00	129.13	TRACK ROLLER
+ r10817	REPAIRS-INTERNAL	11/23/2018	11/23/2018	5	1	0.00	516.52	NEEDS ROLLERS
+ r10694	REPAIRS-INTERNAL	10/30/2018	10/30/2018	1	1	0.00	253.20	TRACK ROLLERS
+ r10650	REPAIRS-SERVICE	10/22/2018	10/22/2018	1	1	0.00	0.00	Service Call for RIGHT SIDE TRACK CAME OFF
+ r10463	REPAIRS-INTERNAL	9/27/2018	9/27/2018	5	1	0.00	566.41	NEEDS NEW PASSENGER SIDE TRACK
+ r10413	REPAIRS-INTERNAL	9/19/2018	9/19/2018	1	1	0.00	62.69	BOOM PIN
+ r10073	REPAIRS-MAINT	7/25/2018	7/25/2018	1	1	0.00	0.00	Maintenance Required
+ r9851	REPAIRS-INTERNAL	6/21/2018	6/25/2018	101	1	0.00	45.00	BLADE REPAIR
+ r9536	REPAIRS-MAINT	5/1/2018	5/1/2018	1	1	0.00	48.67	Maintenance Required
+ r8778	REPAIRS-MAINT	12/8/2017	12/8/2017	1	1	0.00	40.87	Maintenance Required
+ r8772	REPAIRS-MAINT	12/7/2017	12/7/2017	1	1	0.00	48.67	Maintenance Required
+ r8774	REPAIRS-INTERNAL	12/7/2017	12/8/2017	18	1	0.00	25.93	WHEN PRESSING HORN MACHINE STOP MOVING
+ r8536	REPAIRS-MAINT	10/30/2017	10/30/2017	1	1	0.00	0.00	Maintenance Required
+ r8346	REPAIRS-MAINT	10/2/2017	10/2/2017	1	1	0.00	0.00	Maintenance Required
+ r8151	REPAIRS-INTERNAL	9/5/2017	9/13/2017	192	1	0.00	649.08	NO START & HYD LEAK
+ r7542	REPAIRS-MAINT	5/23/2017	5/23/2017	1	1	0.00	47.81	Maintenance Required
+ r7264	REPAIRS-INTERNAL	4/5/2017	5/18/2017	1038	1	0.00	2,414.77	CUSTOMER DAMAGE MACHINE
+ r7042	REPAIRS-INTERNAL	2/27/2017	3/1/2017	46	1	0.00	65.00	BLADE FITTING BROKEN OFF
+ r6973	REPAIRS-SERVICE	2/13/2017	2/13/2017	1	1	0.00	0.00	RIGHT SIDE TRACK CAME OFF
+ r6467	REPAIRS-INTERNAL	11/4/2016	11/8/2016	88	1	0.00	832.28	NEEDS LEFT SIDE TRACK
+ r6433	REPAIRS-MAINT	11/1/2016	11/1/2016	1	1	0.00	39.08	Maintenance Required
+ r5964	REPAIRS-MAINT	8/12/2016	8/12/2016	1	1	0.00	29.88	Maintenance Required
+ r5954	REPAIRS-MAINT	8/11/2016	8/11/2016	1	1	0.00	63.18	Maintenance Required
+ r5889	REPAIRS-INTERNAL	8/2/2016	8/11/2016	224	1	0.00	2,352.11	HIGH IDLE IS STUCK AND BOOM CYLINDER LEAKING
+ r5789	REPAIRS-MAINT	7/15/2016	7/15/2016	1	1	0.00	0.00	Maintenance Required
+ r5790	REPAIRS-SERVICE	7/15/2016	7/15/2016	1	1	0.00	0.00	Service Call for RECALIBRATE THE THROTTLE SWITCH
+ r5720	REPAIRS-INTERNAL	7/5/2016	7/6/2016	14	1	0.00	0.00	CHECK GPS
+ r5567	REPAIRS-INTERNAL	6/9/2016	6/9/2016	1	1	0.00	35.77	BOOM CYLINDER TUBELINE

5453 - EXCAVATOR E-42-BOBCAT

10/17/2019

Contract	Repairs	Broken	Repaired	Hours	Qty	Amount	Repair Cost	Contract Info
+ r5400	REPAIRS-INTERNAL	5/17/2016	5/17/2016	1	1	0.00	0.00	BLADE CYLINDER FITTING
+ r5276	REPAIRS-SERVICE	4/27/2016	4/27/2016	1	1	0.00	0.00	Service Call for MACHINE WOULD NOT START
+ r5074	REPAIRS-INTERNAL	3/21/2016	4/15/2016	598	1	0.00	190.00	blade split on the bottom part
+ r5044	REPAIRS-INTERNAL	3/15/2016	3/17/2016	45	1	0.00	53.74	SIDE COVER DOOR BRACKET
+ r4841	REPAIRS-MAINT	2/3/2016	2/3/2016	1	1	0.00	94.01	Maintenance Required
+ r4842	REPAIRS-INTERNAL	2/3/2016	2/4/2016	25	1	0.00	0.00	BUCKET CYLINDER ROD DAMAGED
+ r4591	REPAIRS-SERVICE	12/8/2015	12/8/2015	1	1	0.00	0.00	Service Call for BATTERY CABLES WERE LOOSE
+ r4087	REPAIRS-INTERNAL	9/1/2015	9/1/2015	1	1	0.00	43.74	BROKEN LIGHT ON BOOM
+ r3920	REPAIRS-MAINT	8/5/2015	8/5/2015	1	1	0.00	43.97	Maintenance Required
+ r3887	REPAIRS-INTERNAL	7/31/2015	8/3/2015	71	1	0.00	87.46	RIGHT SIDE TOP TRACK ROLLER MISSING
+ r3692	REPAIRS-INTERNAL	7/6/2015	7/17/2015	263	1	0.00	2,064.70	HYDRAULIC LEAK
+ r3442	REPAIRS-MAINT	4/23/2015	4/23/2015	1	1	0.00	98.86	Maintenance Required
+ r3251	REPAIRS-SERVICE	4/1/2015	4/1/2015	1	1	0.00	0.00	Service Call for TRACK WAS KNOCKED OFF BY CUSTO
+ r3245	REPAIRS-SERVICE	3/31/2015	3/31/2015	1	1	0.00	10.55	Service Call for FUEL ISSUE
+ r3144	REPAIRS-INTERNAL	3/10/2015	3/11/2015	17	1	0.00	79.35	DRIVER SIDE TOP ROLLER BAD
+ r3075	REPAIRS-SERVICE	2/24/2015	2/24/2015	1	1	0.00	88.56	Service Call for BATTERY
+ r2738	REPAIRS-MAINT	12/4/2014	12/4/2014	1	1	0.00	98.35	Maintenance Required
+ r2693	REPAIRS-INTERNAL	12/1/2014	12/1/2014	1	1	0.00	96.12	AAAAAA
+ r2681	REPAIRS-INTERNAL	11/28/2014	11/28/2014	1	1	0.00	96.12	NOT STARTING
+ r2243	REPAIRS-MAINT	8/20/2014	8/20/2014	1	1	0.00	95.33	Maintenance Required
+ r2137	REPAIRS-SERVICE	7/30/2014	7/30/2014	1	1	0.00	1,000.00	Service Call for RIGHT SIDE TRACK
+ r2071	REPAIRS-INTERNAL	7/14/2014	7/14/2014	1	1	0.00	32.76	SAFETY ARM BEARING
+ r2049	REPAIRS-SERVICE	7/10/2014	7/10/2014	1	1	0.00	68.00	Service Call for BAD BATTERY
+ r1934	REPAIRS-MAINT	6/3/2014	6/3/2014	1	1	0.00	93.14	Maintenance Required
+ r1375	REPAIRS-MAINT	1/27/2014	1/27/2014	1	1	0.00	93.14	AIR, OIL, FUEL FILTER SERVICE
+ r1376	REPAIRS-MAINT	1/27/2014	1/27/2014	1	1	0.00	63.30	HYDRAULIC FILTER SERVICE
+ r457	REPAIRS-INTERNAL	5/17/2013	5/17/2013	2	1	0.00	0.00	HYD ON BLADE FUNCTION
+ r420	REPAIRS-MAINT	5/6/2013	5/6/2013	1	1	0.00	46.73	Maintenance Required