

5795 - BOBCAT T-550 TRACK SKID STEER

#1 A70511068

10/17/2019

Contract	Repairs	Broken	Repaired	Hours	Qty	Amount	Repair Cost	Contract Info
+ r13054	REPAIRS-INTERNAL	10/16/2019	11/13/2019	672	1	0.00	0.00	SOLD MACHINES
+ r13041	REPAIRS-INTERNAL	10/15/2019	10/17/2019	47	1	0.00	0.00	DEAD BATTERY AGAIN, IT MUST HAVE A DRAW
+ r12991	REPAIRS-INTERNAL	10/8/2019	10/9/2019	19	1	0.00	62.45	DEAD BATTERY
+ r12972	REPAIRS-INTERNAL	10/7/2019	10/7/2019	1	1	0.00	31.90	GROUND WIRE ISSUE
+ r12867	REPAIRS-SERVICE	9/23/2019	9/23/2019	1	1	0.00	0.00	Service Call for MACHINE WOULD NOT START (BROK
+ r12460	REPAIRS-INTERNAL	7/26/2019	7/26/2019	1	1	0.00	0.00	DONT START
+ r12374	REPAIRS-MAINT	7/16/2019	7/16/2019	1	1	0.00	96.89	Maintenance Required
+ r12335	REPAIRS-INTERNAL	7/11/2019	7/11/2019	3	1	0.00	38.63	SERVICES
+ r12331	REPAIRS-INTERNAL	7/10/2019	7/10/2019	4	1	0.00	22.15	CUSTOMER DAMAGE
+ r12269	REPAIRS-INTERNAL	6/28/2019	7/1/2019	63	1	0.00	41.65	CUSTOMER BROKE THE BOBTACH AND LEVER HARDV
+ r11882	REPAIRS-INTERNAL	5/10/2019	5/16/2019	143	1	0.00	262.95	MUFFLER BROKE
+ r11879	REPAIRS-INTERNAL	5/9/2019	5/10/2019	22	1	0.00	409.62	HYDRAULIC LEAK ON MACHINE MARK KNOWS
+ r11591	REPAIRS-INTERNAL	3/28/2019	4/3/2019	141	1	0.00	2,342.52	NEEDS TRACKS AND LFT ARM SEAL KITS
+ r11407	REPAIRS-INTERNAL	3/1/2019	3/1/2019	1	1	0.00	100.00	AUX QUICK COUPLERS LEAKING
+ r11408	REPAIRS-INTERNAL	3/1/2019	3/4/2019	68	1	0.00	175.93	BROKEN PIVOT PINS ON BOBTACH
+ r11380	REPAIRS-MAINT	2/27/2019	2/27/2019	1	1	0.00	37.40	Maintenance Required
+ r11252	REPAIRS-INTERNAL	2/5/2019	2/5/2019	1	1	0.00	20.20	ALTERNATOR BELT
+ r11235	REPAIRS-SERVICE	2/4/2019	2/4/2019	1	1	0.00	0.00	Service Call for ALTERNATOR BELT MAKING NOISE
+ r11192	REPAIRS-INTERNAL	1/29/2019	1/29/2019	1	1	0.00	184.26	BRAKE COIL VALVE
+ r11111	REPAIRS-INTERNAL	1/15/2019	1/17/2019	40	1	0.00	56.25	PIVOT PIN NUT MISSING
+ r10996	REPAIRS-INTERNAL	12/21/2018	1/15/2019	595	1	0.00	631.06	HYD LEAK
+ r10892	REPAIRS-SERVICE	12/3/2018	12/3/2018	1	1	0.00	0.00	Service Call for DOES NOT START
+ r10804	REPAIRS-SERVICE	11/19/2018	11/19/2018	1	1	0.00	0.00	Service Call for WILL NOT START
+ r10579	REPAIRS-MAINT	10/12/2018	10/12/2018	1	1	0.00	38.15	Maintenance Required
+ r10508	REPAIRS-SERVICE	10/4/2018	10/4/2018	1	1	0.00	6.00	Service Call for LIFTING ARMS ARE NOT GOING ALL TH
+ r10349	REPAIRS-INTERNAL	9/5/2018	9/5/2018	5	1	0.00	0.00	SWAPPING TRACKS
+ r10223	REPAIRS-INTERNAL	8/16/2018	8/16/2018	1	1	0.00	0.00	BOBTACH PIN NUT MISSING
+ r10215	REPAIRS-INTERNAL	8/15/2018	8/16/2018	20	1	0.00	0.00	both bucket cealinder leaking
+ r10049	REPAIRS-SERVICE	7/23/2018	7/23/2018	1	1	0.00	89.00	Service Call for REPLACED THE BATTERY
+ r9968	REPAIRS-SERVICE	7/9/2018	7/9/2018	1	1	0.00	44.11	Service Call for LEFT BUCKET TILT CYLINDER HOSE BR
+ r9634	REPAIRS-MAINT	5/16/2018	5/16/2018	1	1	0.00	92.61	Maintenance Required
+ r9617	REPAIRS-MAINT	5/14/2018	5/14/2018	1	1	0.00	39.70	Maintenance Required
+ r9405	REPAIRS-SERVICE	4/10/2018	4/10/2018	1	1	0.00	127.14	Service Call for AUX CONNECTION BROKE
+ r9117	REPAIRS-SERVICE	2/23/2018	2/23/2018	1	1	0.00	0.00	Service Call for LEFT TRACK CAME OFF
+ r8811	REPAIRS-INTERNAL	12/14/2017	12/14/2017	3	1	0.00	0.00	DRIVE BELD BAD

5795 - BOBCAT T-550 TRACK SKID STEER

Contract	Repairs	Broken	Repaired	Hours	Qty	Amount	Repair Cost	Contract Info
+ r8716	REPAIRS-INTERNAL	12/1/2017	12/4/2017	73	1	0.00	311.34	DRIVE BELT IS LOOSE
+ r8310	REPAIRS-MAINT	9/27/2017	9/27/2017	1	1	0.00	41.98	Maintenance Required
+ r8307	REPAIRS-INTERNAL	9/26/2017	9/26/2017	1	1	0.00	559.27	AIR DUCT AND BACK WINDOW
+ r7541	REPAIRS-INTERNAL	5/23/2017	5/23/2017	6	1	0.00	1,036.00	NEEDS NEW TRACKS & BACK UP ALARM
+ r7315	REPAIRS-INTERNAL	4/17/2017	4/17/2017	1	1	0.00	1,789.34	BOBTACH WAS BENT AND ALL THE BUSHINGS WERE
+ r7239	REPAIRS-SERVICE	3/31/2017	3/31/2017	1	1	0.00	0.00	Service Call for DRIVE BELT
+ r7228	REPAIRS-INTERNAL	3/30/2017	4/14/2017	359	1	0.00	0.00	BOBTACH BENT BOLT MISSING TO HOLD IT ON
+ r7060	REPAIRS-SERVICE	3/3/2017	3/3/2017	1	1	0.00	269.00	Service Call for DRIVE BELT, IDLER PULLY
+ r7021	REPAIRS-MAINT	2/22/2017	2/22/2017	1	1	0.00	108.44	Maintenance Required
+ r6983	REPAIRS-INTERNAL	2/15/2017	2/15/2017	7	1	0.00	0.00	NEED A NEW DRIVE BELT
+ r6881	REPAIRS-INTERNAL	1/26/2017	1/27/2017	24	1	0.00	58.30	NEEDS NEW BATTERY
+ r6753	REPAIRS-INTERNAL	12/29/2016	1/2/2017	101	1	0.00	0.00	BUCKET DOES NOT RAISE
+ r6704	REPAIRS-INTERNAL	12/14/2016	12/16/2016	46	1	0.00	42.40	FUEL GAUGE ISSUE
+ r6539	REPAIRS-MAINT	11/15/2016	11/15/2016	1	1	0.00	39.21	Maintenance Required
+ r5753	REPAIRS-MAINT	7/11/2016	7/11/2016	1	1	0.00	39.39	Maintenance Required
+ r5704	REPAIRS-INTERNAL	7/2/2016	7/5/2016	32	1	0.00	0.00	AUGER STAYING STUCK
+ r4688	REPAIRS-MAINT	12/29/2015	12/29/2015	1	1	0.00	46.00	Maintenance Required
+ r4387	REPAIRS-MAINT	10/23/2015	10/23/2015	1	1	0.00	81.72	Maintenance Required
+ r4146	REPAIRS-INTERNAL	9/11/2015	9/11/2015	1	1	0.00	102.48	PIVOT PINS
+ r3943	REPAIRS-MAINT	8/10/2015	8/10/2015	1	1	0.00	36.41	Maintenance Required
+ r3027	REPAIRS-MAINT	2/12/2015	2/12/2015	1	1	0.00	78.61	Maintenance Required
+ r2752	REPAIRS-INTERNAL	12/8/2014	12/9/2014	16	1	0.00	8.98	BUCKET FITTING LEAKING
+ r2349	REPAIRS-MAINT	9/11/2014	9/11/2014	1	1	0.00	120.73	Maintenance Required
+ r2163	REPAIRS-MAINT	8/5/2014	8/5/2014	1	1	0.00	42.18	Maintenance Required
+ r1712	REPAIRS-MAINT	4/22/2014	4/22/2014	1	1	0.00	66.11	AIR, OIL, FUEL FILTER SERVICE
+ r1535	REPAIRS-SERVICE	3/6/2014	3/6/2014	1	1	0.00	0.00	MONTHLY SERVICE CHECKUP
+ r1265	REPAIRS-MAINT	1/2/2014	1/2/2014	1	1	0.00	66.11	AIR, OIL, FUEL FILTER SERVICE
+ r838	REPAIRS-SERVICE	8/22/2013	8/22/2013	1	1	0.00	0.00	MONTHLY SERVICE CHECKUP
+ r705	REPAIRS-MAINT	7/17/2013	7/17/2013	1	1	0.00	25.64	AIR, OIL, FUEL FILTER SERVICE
+ r706	REPAIRS-MAINT	7/17/2013	7/17/2013	1	1	0.00	0.00	Maintenance Required