



901 West 94th Street
 Minneapolis MN 55420-4236



Minnesota 800-352-2812
 Iowa 800-342-7002
 Missouri 800-342-7002
 Wisconsin 800-342-7002

Customer BANK IOWA
 1150 JORDAN CREEK PKWY
 WEST DES MOINES, IA 50266-5831
 515-225-0710

Service Estimate

Estimate Number SE000003933
Estimate Date 7/23/2021
Service Call Number SC00063411
Account Number C002900
Expiration Date 8/22/2021
Page 1 / 2
Salesperson
Salesperson Phone
Salesperson Email

Contact
Contact Phone
Contact Email

Equipment:

Serial Number	Make	Model	Customer Equipment Number	Equipment Number
YYZ00842	AA	259B3	40	S20443
SC00063411-003 - Replace - Track Assembly				3,826.92

Notes
 Recommend replacing tracks due to wear and splits in certain spots.

Equipment:

Serial Number	Make	Model	Customer Equipment Number	Equipment Number
YYZ00842	AA	259B3	40	S20443
SC00063411-004 - Replace - Bogie				2,531.30

Notes
 Found six bogies/rollers between both sides of the undercarriage that should be replaced due to failed seals.

Equipment:

Serial Number	Make	Model	Customer Equipment Number	Equipment Number
YYZ00842	AA	259B3	40	S20443
SC00063411-005 - Repair - Loader Frame Bore - Lower				2,866.66

Notes
 Pin bores on work tool coupler plate have excessive wear, recommend replacing coupler plate, installing new pins.

Equipment:

Serial Number	Make	Model	Customer Equipment Number	Equipment Number
YYZ00842	AA	259B3	40	S20443
SC00063411-006 - Repair - Cab Door Glass				612.40

Notes
 Cut out broken center section of glass on cab door and install new glass.



901 West 94th Street
 Minneapolis MN 55420-4236



Estimate Number	Service Call Number	Page
SE000003933	SC00063411	2 / 2

Equipment:

Serial Number	Make	Model	Customer Equipment Number	Equipment Number
YYZ00842	AA	259B3	40	S20443
SC00063411-007 - Replace - Windshield Wiper				246.83

Notes
 Wiper arm and wiper blade need to be replaced.

Equipment:

Serial Number	Make	Model	Customer Equipment Number	Equipment Number
YYZ00842	AA	259B3	40	S20443
SC00063411-008 - Replace - Cab Window Glass - Upper				385.17

Notes
 Window on top of ROPS is missing, install new window.

Subtotal	\$10,469.28
Sales Tax	\$0.00
Total	\$10,469.28

Subject to additional taxes and fees