

5434 - EXCAVATOR E-42-BOBCAT

6

AL3212989

10/17/2019

Contract	Repairs	Broken	Repaired	Hours	Qty	Amount	Repair Cost	Contract Info
+ r13054	REPAIRS-INTERNAL	10/16/2019	11/13/2019	672	1	0.00	0.00	SOLD MACHINES
+ r12701	REPAIRS-INTERNAL	8/30/2019	8/30/2019	2	1	0.00	0.00	GPS ISSUE
+ r12098	REPAIRS-MAINT	6/6/2019	6/6/2019	1	1	0.00	102.12	Maintenance Required
+ r12081	REPAIRS-INTERNAL	6/4/2019	6/5/2019	22	1	0.00	687.00	TRACK TOP ROLLER, IDLER ROLLER
+ r11391	REPAIRS-MAINT	2/28/2019	2/28/2019	1	1	0.00	0.00	Maintenance Required
+ r11131	REPAIRS-INTERNAL	1/21/2019	1/21/2019	1	1	0.00	96.35	LIGHTS
+ r11104	REPAIRS-INTERNAL	1/15/2019	1/15/2019	3	1	0.00	294.39	BAD FRONT TRACK ROLLER
+ r10580	REPAIRS-MAINT	10/12/2018	10/12/2018	1	1	0.00	56.55	Maintenance Required
+ r10268	REPAIRS-INTERNAL	8/22/2018	8/22/2018	4	1	0.00	68.83	ARM CYL SEAL KIT
+ r9952	REPAIRS-MAINT	7/6/2018	7/6/2018	1	1	0.00	54.88	Maintenance Required
+ r9883	REPAIRS-INTERNAL	6/27/2018	6/28/2018	21	1	0.00	0.00	ROCKER ARM PEDAL
+ r9654	REPAIRS-INTERNAL	5/17/2018	5/23/2018	142	1	0.00	798.26	NEEDS SOME SPROCKETS
+ r9641	REPAIRS-INTERNAL	5/16/2018	5/17/2018	24	1	0.00	126.60	FOOT CONTROLS NEED TO BE ADJUSTED
+ r9318	REPAIRS-INTERNAL	3/26/2018	3/26/2018	1	1	0.00	0.00	ROCKARMS NEED TO BE LOOK OVER
+ r9299	REPAIRS-MAINT	3/23/2018	3/23/2018	1	1	0.00	47.89	Maintenance Required
+ r9278	REPAIRS-INTERNAL	3/20/2018	3/22/2018	44	1	0.00	207.04	ROCKARMS LEAKING BAD
+ r8995	REPAIRS-INTERNAL	1/26/2018	1/26/2018	1	1	0.00	82.78	BLADE CYLINDER LEAKING
+ r8932	REPAIRS-SERVICE	1/12/2018	1/12/2018	1	1	0.00	0.00	Service Call for SAFETY ARM BEARING WAS LOOSE
+ r8892	REPAIRS-INTERNAL	1/2/2018	1/8/2018	141	1	0.00	30.25	ROB PARTS TO FIX E50
+ r8566	REPAIRS-MAINT	11/3/2017	11/3/2017	1	1	0.00	48.67	Maintenance Required
+ r8350	REPAIRS-INTERNAL	10/3/2017	10/3/2017	5	1	0.00	20.00	SAFE ARMS ROLLER BEARING BVAD
+ r8250	REPAIRS-INTERNAL	9/18/2017	9/20/2017	46	1	0.00	106.06	BAD BOTTOM ROLLER DRIVE SIDE
+ r7887	REPAIRS-MAINT	7/18/2017	7/18/2017	1	1	0.00	50.11	Maintenance Required
+ r7328	REPAIRS-MAINT	4/17/2017	4/17/2017	1	1	0.00	39.47	Maintenance Required
+ r7181	REPAIRS-INTERNAL	3/23/2017	3/24/2017	24	1	0.00	0.00	TOP GLASS BROKEN ON MACHINE
+ r6791	REPAIRS-INTERNAL	1/9/2017	1/9/2017	5	1	0.00	0.00	DONT START
+ r6563	REPAIRS-SERVICE	11/21/2016	11/21/2016	1	1	0.00	27.44	Service Call for SAFETY ARM BEARING
+ r6507	REPAIRS-INTERNAL	11/10/2016	11/11/2016	22	1	0.00	100.66	PASSINGER SIDE ROLLER BAD
+ r6431	REPAIRS-MAINT	11/1/2016	11/1/2016	1	1	0.00	80.21	Maintenance Required
+ r6316	REPAIRS-SERVICE	10/14/2016	10/14/2016	1	1	0.00	0.00	Service Call for ALEX REPLACED A BROKEN TOOTH ON
+ r5728	REPAIRS-MAINT	7/7/2016	7/7/2016	1	1	0.00	0.00	Maintenance Required
+ r5257	REPAIRS-MAINT	4/25/2016	4/25/2016	1	1	0.00	85.88	Maintenance Required
+ r4631	REPAIRS-MAINT	12/15/2015	12/15/2015	1	1	0.00	52.13	Maintenance Required
+ r4200	REPAIRS-INTERNAL	9/23/2015	9/23/2015	1	1	0.00	1,000.00	TRACK
+ r4201	REPAIRS-MAINT	9/23/2015	9/23/2015	1	1	0.00	72.09	Maintenance Required

5434 - EXCAVATOR E-42-BOBCAT

10/17/2019

Contract	Repairs	Broken	Repaired	Hours	Qty	Amount	Repair Cost	Contract Info
+ r4190	REPAIRS-INTERNAL	9/21/2015	9/23/2015	43	1	0.00	0.00	NEEDS SOME TLC
+ r4181	REPAIRS-SERVICE	9/18/2015	9/18/2015	1	1	0.00	89.00	Service Call for BATTERY
+ r4122	REPAIRS-MAINT	9/4/2015	9/4/2015	1	1	0.00	34.77	Maintenance Required
+ r4066	REPAIRS-SERVICE	8/28/2015	8/28/2015	1	1	0.00	1,050.00	Service Call for BROKEN TRACK
+ r4067	REPAIRS-MAINT	8/28/2015	8/28/2015	1	1	0.00	93.94	Maintenance Required
+ r3829	REPAIRS-SERVICE	7/27/2015	7/27/2015	1	1	0.00	61.00	Service Call for REPLACED BUCKET TILT CYL HOSE AND
+ r3790	REPAIRS-SERVICE	7/20/2015	7/20/2015	1	1	0.00	25.57	Service Call for MONTHLY CHECK UP
+ r3695	REPAIRS-INTERNAL	7/7/2015	7/7/2015	1	1	0.00	2,119.94	BOOM CYLINDER
+ r3621	REPAIRS-INTERNAL	6/23/2015	6/26/2015	75	1	0.00	0.00	boom cylinder leaking
+ r3622	REPAIRS-MAINT	6/23/2015	6/23/2015	1	1	0.00	53.19	Maintenance Required
+ r3463	REPAIRS-INTERNAL	5/18/2015	5/18/2015	2	1	0.00	37.92	ARM CEALINDER LEAKING
+ r3011	REPAIRS-INTERNAL	2/9/2015	3/25/2015	1058	1	0.00	2,430.19	CUSTOMER FLIPPED MACHINE
+ r2812	REPAIRS-INTERNAL	12/18/2014	12/22/2014	96	1	0.00	170.00	BLADE REPAIR
+ r2498	REPAIRS-INTERNAL	10/20/2014	10/20/2014	1	1	0.00	1,272.89	UPPER TRACK ROLLERS AND RIGHT SIDE TRACK
+ r2428	REPAIRS-MAINT	10/1/2014	10/1/2014	1	1	0.00	68.46	Maintenance Required
+ r2387	REPAIRS-MAINT	9/23/2014	9/23/2014	1	1	0.00	85.08	Maintenance Required
+ r2370	REPAIRS-SERVICE	9/17/2014	9/17/2014	1	1	0.00	0.00	Service Call for HYDRAULIC LEAK
+ r2132	REPAIRS-SERVICE	7/29/2014	7/29/2014	1	1	0.00	68.00	Service Call for BATTERY
+ r2015	REPAIRS-SERVICE	7/1/2014	7/1/2014	1	1	0.00	32.76	Service Call for SAFETY ARM BEARING
+ r1758	REPAIRS-MAINT	5/1/2014	5/1/2014	1	1	0.00	93.14	AIR, OIL, FUEL FILTER SERVICE
+ r1507	REPAIRS-MAINT	2/25/2014	2/25/2014	1	1	0.00	93.14	AIR, OIL, FUEL FILTER SERVICE
+ r1275	REPAIRS-MAINT	1/3/2014	1/3/2014	1	1	0.00	57.45	HYDRAULIC FILTER SERVICE
+ r1126	REPAIRS-MAINT	11/7/2013	11/7/2013	1	1	0.00	158.14	AIR, OIL, FUEL FILTER SERVICE
+ r1021	REPAIRS-INTERNAL	10/11/2013	11/7/2013	648	1	0.00	0.00	DRIVE MOTOR SPROCKET BOLTS
+ r894	REPAIRS-INTERNAL	9/5/2013	9/5/2013	2	1	0.00	89.06	BROKEN WINDOW
+ r687	REPAIRS-MAINT	7/15/2013	7/15/2013	1	1	0.00	24.02	Maintenance Required