

Lot # 116 VIN DDZ1Z519

## Major Component Repairs

### Engine Repairs

Type of Repairs: REPLACE NOX AND O2 SENSOR 6/29/17

Date of Repairs: \_\_\_\_\_

Repair Bills Attached:

yes

no

### Transmission Repairs

Type of Repairs: \_\_\_\_\_

Date of Repairs: \_\_\_\_\_

Repair Bills Attached:

yes

no

"The above statements are solely and exclusively those of the OWNER of this vehicle and not any other person. Neither the Auctioneer nor the Auction Company is the owner of this vehicle."

 **Taylor & Martin, Inc.**  
AUCTIONEERS

P.O. Box 349, Fremont, NE 68026