Lot # <u> 118</u>	VIN	177	136e
--------------------	-----	-----	------

Major Component Repairs

Engine Repairs		
Type of Repairs:		
Rear Main Se	al	
Clutch		
Flywheel Tui	ned	
Clutch Flywheel Tul Date of Repairs: 10/19		
Repair Bills Attached:	yes	no
Transmis	sion Repairs	
Type of Repairs:		
Date of Repairs:		
Repair Bills Attached:	yes	no

"The above statements are solely and exclusively those of the OWNER of this vehicle and not any other person. Neither the Auctioneer nor the Auction Company is the owner of this vehicle."



P.O. Box 349, Fremont, NE 68026