

# MOTOR VEHICLE PURCHASE AGREEMENT

NO. \_\_\_\_\_

DATE 02-26-04

**REES TRUCK & TRAILER, INC.**  
 3508 5th Ave. So.  
 Ft. Dodge, Iowa 50501  
 (515) 955-7337

BUYER Cedar Falls Construction Co., Inc.  
 CO-BUYER \_\_\_\_\_  
 ADDRESS Box 368  
 CITY Cedar Falls  
 STATE IA ZIP 50613  
 BUYER'S REGISTRATION MONTH \_\_\_\_\_ COUNTY Black Hawk  
 RES. PHONE 319-235-6746 BUS. PHONE \_\_\_\_\_

SALESPERSON Mike Murphy

DESCRIPTION OF PURCHASED VEHICLE:  NEW  USED  DEMO  CAR  TRUCK  VAN

STOCK NO. TU040014 TO BE DELIVERED ON OR ABOUT \_\_\_\_\_  
 YEAR 1999 MAKE MACK MODEL RD688 BODY TYPE \_\_\_\_\_  
 V.I.N. # 1M2P267C8X14040014 COLOR Red TRIM \_\_\_\_\_

|                  |              |  |                 |
|------------------|--------------|--|-----------------|
| PRICE OF VEHICLE | \$ 55,000.00 | TRADE-IN ALLOWANCE AND OTHER CREDITS: YEAR <u>NONE</u> |                 |
| ACCESSORIES      |              | TRADE-IN MAKE  | MODEL BODY TYPE |
|                  |              | PLATE NO.  | V.I.N. #        |
|                  |              | BALANCE OWED TO  |                 |
|                  |              | ADDRESS  |                 |
|                  |              | TRADE-IN ALLOWANCE                                     | \$ -0-          |
|                  |              | LESS BALANCE OWED                                      |                 |
|                  |              | NET TRADE-IN ALLOWANCE OR REMAINING TRADE-IN DEBT      | \$              |
|                  |              | DEPOSIT OR CREDIT BALANCE                              | -0-             |
|                  |              | MANUFACTURER'S REBATE (IF ANY)                         |                 |
|                  |              | <b>TOTAL DOWN PAYMENT (TRANSFER TO LEFT COLUMN)</b>    | <b>\$ -0-</b>   |

V 1009-6268

### BUYER'S TRADE-IN CERTIFICATION

If you are trading in a vehicle, you certify the following:

1. That there is no salvage or repair history on the vehicle title that would affect the value of the vehicle. If there is salvage or repair history on the title, you agree that the dealer may cancel this sale. That to the best of your knowledge, the vehicle was never on a salvage, rebuilt or flood title in this or any other state.
2. That the air bags are intact and in working order.
3. That while you have owned the trade-in, its odometer has not been repaired, replaced, tampered with or altered in any way. That the odometer statement, damage disclosure statement and prior vehicle history which you provided us for your trade-in is true and correct.
4. That the original emission control system (including the catalytic converter) is intact. That the engine and transmission have not been changed from the manufacturer's original specifications. That the trade-in does not have a cracked or defective head, block, power-train or frame.

### DISCLAIMER OF WARRANTY

IF THERE IS A MANUFACTURER'S WARRANTY ON THE VEHICLE YOU ARE BUYING, THE DEALER IS NOT A PARTY TO IT AND IT IS NOT A PART OF THIS CONTRACT. IF WE ARE AUTHORIZED BY THE MANUFACTURER TO PERFORM WARRANTY WORK ON YOUR VEHICLE, WE HOPE THAT YOU ASK US TO PERFORM THE WORK. HOWEVER, THE MANUFACTURER'S WARRANTY IS BETWEEN YOU AND THE MANUFACTURER. AS FAR AS THE DEALER IS CONCERNED, YOU UNDERSTAND THAT THE VEHICLE IS SOLD "AS IS" WITH ALL FAULTS AND THAT WE MAKE NO WARRANTY OF MERCHANTABILITY AND NO WARRANTY THAT THE VEHICLE IS FIT FOR ANY PARTICULAR PURPOSE. (There is additional information in (2) on the back of this contract.)

*Pat Beekle, Vice President*

|  |                               |                     |
|--|-------------------------------|---------------------|
| \$ 55,000.00                                       | CASH PRICE                    | \$ 55,000.00        |
| \$ -   | LESS TRADE-IN ALLOWANCE       |                     |
| \$ -   | LESS MANUFACTURER'S REBATE    |                     |
| \$ 55,000.00                                       | TAXABLE AMOUNT                |                     |
| TAX \$   | TITLE FEE \$15 LICENSE FEE \$ | \$                  |
| LIEN FILING FEE [credit sale only see (1) on back] |                               | \$                  |
| <b>TOTAL CASH DELIVERED PRICE</b>                  |                               | <b>\$ 55,000.00</b> |
| LESS TOTAL DOWN PAYMENT (FROM RIGHT COLUMN)        |                               | \$ -                |
| <b>UNPAID CASH BALANCE DUE ON DELIVERY</b>         |                               | <b>\$ 55,000.00</b> |

OTHER INFORMATION OR TERMS OF SALE.

You understand that this agreement (*including the terms on the back*) is an offer to purchase the vehicle described which will become a binding contract once the dealer has signed it. This document represents the complete agreement between you and the dealer regardless of any other oral, written or prior agreements or representations. However, if you are buying a used vehicle, the information you see on the window form for this vehicle is part of the contract and the information on the window form overrides any contrary provision in this contract.

Iowa law requires us to give you the following notice: You understand that liability insurance coverage which would protect you under the Iowa Motor Vehicle and Safety Responsibility Act IS NOT INCLUDED in your purchase of this motor vehicle.

By signing this contract, you are certifying that you are at least 18 years old (if there are two buyers, that at least one of you is 18 years old), that you have read this contract, front and back, and agree to its terms, and that you have received a copy of it.

Accepted By: *Cindy Rees* Dealer's Authorized Representative

X *Pat Beekle, Vice President* Buyer's Signature Date of Birth \_\_\_\_\_  
 42-0871241 Buyer's Driver's License or F.I.D. No. & Soc. Sec. No. if different from Driver's License No.

X \_\_\_\_\_ Co-Buyer's Signature Date of Birth \_\_\_\_\_  
 \_\_\_\_\_ Co-Buyer's Driver's License or F.I.D. No. & Soc. Sec. No. if different from Drivers License No.

# RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

DATE

3/5/04

D0306937

|   |  |  |  |  |                        |
|---|--|--|--|--|------------------------|
| COMPANY NAME<br><b>Cedar Falls Construction Co., Inc.</b> |  |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |  |                        |
| STREET ADDRESS<br><b>3533 W. Airline Hwy.</b>             |  |  | VEHICLE MAKE<br><b>MAK</b>   |  | MODEL<br><b>RD 688</b> |
| CITY STATE ZIP<br><b>Waterloo, IA 50703</b>               |  |  | YEAR<br><b>1999</b>  |  |                        |
| INSPECTOR'S NAME (Please Print)<br><b>J J ZEIGER</b>      |  |  | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br><b>#33</b>   |  |                        |
| EMPLOYEE NO.  |  |  |  |  |                        |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |    |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓  |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓  |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓  |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | ✓  |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓  |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓  |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |    |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |    |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |    |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount |    |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pin/Upper Plate     |    |        | Tie-Downs         | ✓  |        | Sliders            | ✓  |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | ✓  |        | Headerboard       | ✓  |        |                    |    |        |                       | ✓  |        |
| Safety Chain(s)     |    |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |    |        |                   |    |        |                    | ✓  |        |                       | ✓  |        |

### REMARKS

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE *JJ Zeiger*

DATE 3/5/04

APPLY LABEL TO A CLEAN, DRY SURFACE. LABEL MATERIAL IS GUARANTEED TO LAST A 12-MONTH PERIOD UNDER NORMAL WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.

D0306937

425259

Cedar Falls Construction Co., Inc.

3533 W. Airline Hwy.

Waterloo, IA 50703

DATE

3/7/05

## RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

D4156320

|  |  |             |  |   |                |
|--|--|-------------|--|---|----------------|
| COMPANY NAME<br>Cedar Falls Construction Co. Inc |  |             | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |   |                |
| STREET ADDRESS<br>3533 Airlane Hwy               |  |             | VEHICLE MAKE<br>Mack   |   | MODEL<br>RD688 |
| CITY<br>Waterloo Iowa                            |  | STATE<br>IA | ZIP<br>50703   | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br>#33 |                |
| INSPECTOR'S NAME (Please Print)<br>Troy Buseman  |  |             |  | EMPLOYEE NO.  |                |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       | ✓  |        | <b>EXHAUST</b>    | ✓  |        | <b>STEERING</b>    | ✓  |        | <b>FRAME</b>          | ✓  |        |
| Adjustment          | ✓  |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              |    |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓  |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | ✓  |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓  |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓  |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |    |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |    |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |    |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount |    |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pin/Upper Plate     |    |        | Tie-Downs         | ✓  |        | Sliders            | ✓  |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | ✓  |        | Headerboard       | ✓  |        |                    |    |        |                       | ✓  |        |
| Safety Chain(s)     |    |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |    |        |                   |    |        |                    | ✓  |        |                       | ✓  |        |

REMARKS New brakes rear axle, seals

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE

Troy Buseman

DATE

3/7/05

APPLY LABEL TO A CLEAN, DRY SURFACE.  
LABEL MATERIAL IS GUARANTEED TO LAST  
A 12-MONTH PERIOD UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

D4156920

# RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

DATE  
1/24/06  
D4267718

|  |                    |                     |  |              |                       |
|--|--------------------|---------------------|--|--------------|-----------------------|
| COMPANY NAME<br><u>Cedar Falls Construction</u>        |                    |                     | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |              |                       |
| STREET ADDRESS<br><u>3533 Airline Hwy</u>              |                    |                     | VEHICLE MAKE<br><u>Merck</u>   |              | MODEL<br><u>R0688</u> |
| CITY<br><u>Waterloo</u>                                | STATE<br><u>IA</u> | ZIP<br><u>50703</u> | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br><u>#33</u>   |              |                       |
| INSPECTOR'S NAME (Please Print)<br><u>Troy Buseman</u> |                    |                     |  | EMPLOYEE NO. |                       |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK  | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|-----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |     |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓   |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓   |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓   |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓   |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓   |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓   |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | ✓   |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓   |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓   |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |     |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |     |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |     |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount |     |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pin/Upper Plate     | N/A |        | Tie-Downs         | ✓  |        | Sliders            | ✓  |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | ✓   |        | Headerboard       | ✓  |        |                    |    |        |                       | ✓  |        |
| Safety Chain(s)     | N/A |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |     |        |                   |    |        |                    | ✓  |        |                       | ✓  |        |

### REMARKS

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE Troy Buseman DATE 1/24/06

**APPLY LABEL TO A CLEAN, DRY SURFACE. LABEL MATERIAL IS GUARANTEED TO LAST A 12-MONTH PERIOD UNDER NORMAL WEATHER CONDITIONS.**

**AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.**

D4267718

# RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

DATE

2-14-07

D4945868

|   |  |  |  |  |                       |
|---|--|--|--|--|-----------------------|
| COMPANY NAME<br><b>Cedar Falls Construction Co., Inc.</b> |  |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER DOLLY |  |                       |
| STREET ADDRESS<br><b>PO Box 368</b>                       |  |  | VEHICLE MAKE<br><b>Mack</b>  |  | MODEL<br><b>RD688</b> |
| CITY<br><b>Cedar Falls, IA 50613</b>                      |  |  | YEAR<br><b>1999</b>  |  |                       |
| INSPECTOR'S NAME (Please Print)<br><b>Steve Horstman</b>  |  |  | EMPLOYEE NO.   |  |                       |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK  | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|-----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |     |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓   |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓   |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓   |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓   |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓   |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓   |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | N/A |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓   |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓   |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |     |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |     |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |     |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | N/A |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pin/Upper Plate     | N/A |        | Tie-Downs         | ✓  |        | Sliders            | ✓  |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | ✓   |        | Headerboard       | ✓  |        |                    |    |        |                       | ✓  |        |
| Safety Chain(s)     | N/A |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |     |        |                   |    |        |                    | ✓  |        |                       | ✓  |        |

### REMARKS

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE

Steve Horstman

DATE

2-14-07

**APPLY LABEL TO A CLEAN, DRY SURFACE. LABEL MATERIAL IS GUARANTEED TO LAST A 12-MONTH PERIOD UNDER NORMAL WEATHER CONDITIONS.**

**AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.**

D4945868

Cedar Falls Construction Co., Inc.

PO Box 368

Cedar Falls, IA 50613

DATE

1-29-08

**RECORD OF ANNUAL INSPECTION**

(49 CFR, 396. 17-23)

Prepare Separate Report for Each Vehicle Inspected

D6079628

|   |  |  |  |  |                       |
|---|--|--|--|--|-----------------------|
| COMPANY NAME<br><b>Cedar Falls Construction Co., Inc.</b> |  |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER DOLLY |  |                       |
| STREET ADDRESS<br><b>PO Box 368</b>                       |  |  | VEHICLE MAKE<br><b>Mack</b>  |  | MODEL<br><b>RD688</b> |
| CITY<br><b>Cedar Falls, IA 50613</b>                      |  |  | YEAR<br><b>1999</b>  |  |                       |
| INSPECTOR'S NAME (Please Print)<br><b>Steve Horstman</b>  |  |  | EMPLOYEE NO.<br><b>#33</b>   |  |                       |

**REPORT OF CONDITION** (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK  | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|-----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |     |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓   |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓   |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓   |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓   |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓   |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓   |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | N/A |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓   |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓   |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |     |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | <b>WHEELS/RIM</b>     |    |        |
| <b>COUPLERS</b>     |     |        | Access            | ✓  |        | Springs            | ✓  |        | Fasteners             | ✓  |        |
| Fifth-Wheel & Mount | N/A |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        | Disc/Spoke            | ✓  |        |
| Pin/Upper Plate     | N/A |        | Tie-Downs         | ✓  |        | Sliders            | ✓  |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | ✓   |        | Headerboard       | ✓  |        |                    |    |        |                       | ✓  |        |
| Safety Chain(s)     | N/A |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |     |        |                   |    |        |                    | ✓  |        |                       | ✓  |        |

## REMARKS

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE

Steve Horstman

DATE

1-29-08

APPLY LABEL TO A CLEAN, DRY SURFACE.  
LABEL MATERIAL IS GUARANTEED TO LAST  
A 12-MONTH PERIOD UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

D6079628

Cedar Falls Construction Co., Inc.

PO Box 368

Cedar Falls, IA 50613

# RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

DATE  
12-2-08

D6357232

|   |  |  |  |              |                        |
|---|--|--|--|--------------|------------------------|
| COMPANY NAME<br><b>Cedar Falls Construction Co., Inc.</b> |  |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |              |                        |
| STREET ADDRESS<br><b>PO Box 368</b>                       |  |  | VEHICLE MAKE<br><b>Mack</b>  |              | MODEL<br><b>RD 688</b> |
| CITY<br><b>Cedar Falls, IA 50613</b>                      |  |  | YEAR<br><b>1999</b>  |              |                        |
| STATE<br><b>IA</b>  |  |  | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br><b># 33      398 TPA</b>   |              |                        |
| INSPECTOR'S NAME (Please Print)<br><b>Troy Busema</b>     |  |  |  | EMPLOYEE NO. |                        |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |    |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓  |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓  |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓  |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | NA |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓  |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓  |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |    |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |    |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |    |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | NA |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pin/Upper Plate     | NA |        | Tie-Downs         | ✓  |        | Sliders            | ✓  |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | ✓  |        | Headerboard       | ✓  |        |                    |    |        |                       | ✓  |        |
| Safety Chain(s)     | NA |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |    |        |                   |    |        |                    | ✓  |        |                       | ✓  |        |

### REMARKS

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE Troy Busema      DATE 12-2-08

**APPLY LABEL TO A CLEAN, DRY SURFACE. LABEL MATERIAL IS GUARANTEED TO LAST A 12-MONTH PERIOD UNDER NORMAL WEATHER CONDITIONS.**

**AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.**

D6357232

Cedar Falls Construction Co., Inc.

PO Box 368

Cedar Falls, IA 50613

DATE

**RECORD OF ANNUAL INSPECTION**

(49 CFR, 396. 17-23)

Prepare Separate Report for Each Vehicle Inspected

1-15-10  
06685058

|  |  |             |  |  |  |  |  |              |  |
|--|--|-------------|--|--|--|--|--|--------------|--|
| COMPANY NAME<br>Cedar Falls Construction Co., Inc. |  |             |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |  |  |  |              |  |
| STREET ADDRESS<br>PO Box 368                       |  |             |  | VEHICLE MAKE<br>Mack   |  | MODEL<br>RD688   |  | YEAR<br>1999 |  |
| CITY<br>Cedar Falls                                |  | STATE<br>IA |  | ZIP<br>50613   |  | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br># 33 |  |              |  |
| INSPECTOR'S NAME (Please Print)<br>Steve Horstman  |  |             |  |  |  | EMPLOYEE NO.   |  |              |  |

**REPORT OF CONDITION** (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK  | REPAIR |                   | OK | REPAIR |                    | OK  | REPAIR |                       | OK | REPAIR |
|---------------------|-----|--------|-------------------|----|--------|--------------------|-----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |     |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |     |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓   |        | Leaks             | ✓  |        | Adjustment         | ✓   |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓   |        | Placement         | ✓  |        | Column/Gear        | ✓   |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓   |        | <b>LIGHTING</b>   |    |        | Axle               | ✓   |        |                       |    |        |
| Hose/Tubing         | ✓   |        | Headlights        | ✓  |        | Linkage            | ✓   |        | <b>TIRES</b>          |    |        |
| Lining              | ✓   |        | Tail/Stop         | ✓  |        | Power Steering     | ✓   |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓   |        | Clearance/Marker  | ✓  |        | Other              |     |        | Inflation             | ✓  |        |
| Trailer Air Supply  | N/A |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |     |        | Damage                | ✓  |        |
| Compressor          | ✓   |        | Reflectors        | ✓  |        | Tank(s)            | ✓   |        | Other                 |    |        |
| Parking Brakes      | ✓   |        | Other             |    |        | Lines              | ✓   |        |                       |    |        |
| Other               |     |        |                   |    |        |                    |     |        | <b>WHEELS/RIM</b>     |    |        |
|                     |     |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |     |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |     |        | Access            | ✓  |        | Springs            | ✓   |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | N/A |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓   |        |                       |    |        |
| Pin/Upper Plate     | ✓   |        | Tie-Downs         | ✓  |        | Sliders            | N/A |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | N/A |        | Headerboard       | ✓  |        |                    |     |        |                       | ✓  |        |
| Safety Chain(s)     | N/A |        | Other             |    |        | <b>MIRRORS</b>     |     |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |     |        |                   |    |        |                    | ✓   |        |                       | ✓  |        |

## REMARKS

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE

Steve Horstman

DATE

1-15-10

APPLY LABEL TO A CLEAN, DRY SURFACE.  
LABEL MATERIAL IS GUARANTEED TO LAST  
A 12-MONTH PERIOD UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

06685058

Cedar Falls Construction Co., Inc.

3533 W. Airline Hwy.

Waterloo, IA 50703



DATE

1-18-2011

## RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

D7493880

|   |  |  |  |                    |                 |
|---|--|--|--|--------------------|-----------------|
| COMPANY NAME<br>Cedar Falls Construction Co., Inc.    |  |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |                    |                 |
| STREET ADDRESS<br>PO Box 368                          |  |  | VEHICLE MAKE<br>MACK   |                    | MODEL<br>RD 688 |
| CITY<br>Cedar Falls, IA 50613                         |  |  | YEAR<br>1999   |                    |                 |
| STATE<br>IA   |  |  | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br>33   |                    |                 |
| INSPECTOR'S NAME (Please Print)<br>DAVID J. CRYSUP SR |  |  |  | EMPLOYEE NO.<br>16 |                 |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK  | REPAIR |                   | OK | REPAIR |                    | OK  | REPAIR |                       | OK | REPAIR |
|---------------------|-----|--------|-------------------|----|--------|--------------------|-----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |     |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |     |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓   |        | Leaks             | ✓  |        | Adjustment         | ✓   |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓   |        | Placement         | ✓  |        | Column/Gear        | ✓   |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓   |        | <b>LIGHTING</b>   |    |        | Axle               | ✓   |        |                       |    |        |
| Hose/Tubing         | ✓   |        | Headlights        | ✓  |        | Linkage            | ✓   |        | <b>TIRES</b>          |    |        |
| Lining              | ✓   |        | Tail/Stop         | ✓  |        | Power Steering     | ✓   |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓   |        | Clearance/Marker  | ✓  |        | Other              |     |        | Inflation             | ✓  |        |
| Trailer Air Supply  | N/A |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |     |        | Damage                | ✓  |        |
| Compressor          | ✓   |        | Reflectors        | ✓  |        | Tank(s)            | ✓   |        | Other                 |    |        |
| Parking Brakes      | ✓   |        | Other             |    |        | Lines              | ✓   |        |                       |    |        |
| Other               |     |        |                   |    |        |                    |     |        | <b>WHEELS/RIM</b>     |    |        |
|                     |     |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |     |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |     |        | Access            | ✓  |        | Springs            | ✓   |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | N/A |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓   |        |                       |    |        |
| Pin/Upper Plate     | ✓   |        | Tie-Downs         | ✓  |        | Sliders            | N/A |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | N/A |        | Headerboard       | ✓  |        |                    |     |        |                       | ✓  |        |
| Safety Chain(s)     | N/A |        | Other             |    |        | <b>MIRRORS</b>     |     |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |     |        |                   |    |        |                    | ✓   |        |                       | ✓  |        |

## REMARKS

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

QUALIFIED INSPECTOR'S SIGNATURE

DATE

1-18-2011

APPLY LABEL TO A CLEAN, DRY SURFACE.  
USE WITH AN OVERLAMINATE (221-SN) TO  
IMPROVE DURABILITY UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

D7493880

USDOT425259

Cedar Falls Construction Co., Inc.

3533 W. Airline Hwy.

Waterloo, IA 50703

DATE

## RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

D8466389

|  |             |  |                                       |
|--|-------------|--|---------------------------------------|
| COMPANY NAME<br>Cedar Falls Construction Co., Inc. |             | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |                                       |
| STREET ADDRESS<br>PO Box 368                       |             | VEHICLE MAKE<br>MACK   | MODEL<br>RD488                        |
| CITY<br>Cedar Falls, IA                            | STATE<br>IA | ZIP<br>50613   | YEAR<br>1999                          |
| INSPECTOR'S NAME (Please Print)<br>Dylan M. Conner |             |  | EMPLOYEE NO.<br>#33 1M2P267C8XMO40014 |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK  | REPAIR |                   | OK | REPAIR |                    | OK  | REPAIR |                       | OK | REPAIR |
|---------------------|-----|--------|-------------------|----|--------|--------------------|-----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |     |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |     |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓   |        | Leaks             | ✓  |        | Adjustment         | ✓   |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓   |        | Placement         | ✓  |        | Column/Gear        | ✓   |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓   |        | <b>LIGHTING</b>   |    |        | Axle               | ✓   |        |                       |    |        |
| Hose/Tubing         | ✓   |        | Headlights        | ✓  |        | Linkage            | ✓   |        | <b>TIRES</b>          |    |        |
| Lining              | ✓   |        | Tail/Stop         | ✓  |        | Power Steering     | ✓   |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓   |        | Clearance/Marker  | ✓  |        | Other              |     |        | Inflation             | ✓  |        |
| Trailer Air Supply  | N/A |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |     |        | Damage                | ✓  |        |
| Compressor          | ✓   |        | Reflectors        | ✓  |        | Tank(s)            | ✓   |        | Other                 |    |        |
| Parking Brakes      | ✓   |        | Other             |    |        | Lines              | ✓   |        |                       |    |        |
| Other               |     |        |                   |    |        |                    |     |        | <b>WHEELS/RIM</b>     |    |        |
|                     |     |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |     |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |     |        | Access            | ✓  |        | Springs            | ✓   |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | N/A |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓   |        |                       |    |        |
| Pin/Upper Plate     | ✓   |        | Tie-Downs         | ✓  |        | Sliders            | N/A |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | N/A |        | Headerboard       | ✓  |        |                    |     |        |                       | ✓  |        |
| Safety Chain(s)     | N/A |        | Other             |    |        | <b>MIRRORS</b>     |     |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |     |        |                   |    |        |                    | ✓   |        |                       | ✓  |        |

## REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

Dylan M. Conner

DATE

12-1-11

APPLY LABEL TO A CLEAN, DRY SURFACE.  
USE WITH AN OVERLAMINATE (221-SN) TO  
IMPROVE DURABILITY UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

© Copyright 2010 J. J. KELLER & ASSOCIATES, INC.®, Neenah, WI • USA  
(800) 327-6868 • jkeller.com • Printed in the United States

401-FC-O2 3136  
(Rev. 6/10)

D8466389

Cedar Falls Construction Co., Inc.

PO Box 368

Cedar Falls, IA 50613

DATE

11-13-12

## RECORD OF ANNUAL INSPECTION

(49 CFR, 396. 17-23)

Prepare Separate Report for Each Vehicle Inspected

D8466468

|   |             |  |                |
|---|-------------|--|----------------|
| COMPANY NAME<br>Cedar Falls Construction Co., Inc.                              |             | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |                |
| STREET ADDRESS<br>PO Box 368  |             | VEHICLE MAKE<br>MACK   | MODEL<br>RD688 |
| CITY<br>Cedar Falls, IA   | STATE<br>IA | ZIP<br>50613   | YEAR<br>99'    |
| INSPECTOR'S NAME (Please Print)<br>DYLAN M. CONNER                              |             |  | EMPLOYEE NO.   |
| VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br>1M8P367C8XM040014 |             |  |                |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                       | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-----------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |    |        | <b>EXHAUST</b>        |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓  |        | Leaks                 | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement             | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>       |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights            | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓  |        | Tail/Stop             | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓  |        | Clearance/Marker      | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | ✓  |        | Identification        | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓  |        | Reflectors            | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓  |        | Other                 | ✓  |        | Lines              | ✓  |        |                       |    |        |
| Other               |    |        | AIR<br>#2038<br>#2039 |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
| <b>COUPLERS</b>     |    |        | <b>CAB/BODY</b>       |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| Fifth-Wheel & Mount | NA |        | Access                | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Pin/Upper Plate     | ✓  |        | Eqpt./Load Secure     | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pintle-Hook/Eye     | NA |        | Tie-Downs             | ✓  |        | Sliders            | NA |        | <b>WINDSHIELD</b>     |    |        |
| Safety Chain(s)     | NA |        | Headerboard           | ✓  |        |                    |    |        |                       | ✓  |        |
|                     |    |        | Other                 |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |    |        |                       |    |        |                    | ✓  |        |                       | ✓  |        |

## REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

Dylan M. Conner

DATE

11-13-12

APPLY LABEL TO A CLEAN, DRY SURFACE.  
USE WITH AN OVERLAMINATE (221-SN) TO  
IMPROVE DURABILITY UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

D8466468

DATE

12-2-13

## RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

D9585333

|  |             |              |   |  |  |
|--|-------------|--------------|---|--|--|
| COMPANY NAME<br>Cedar Falls Construction Co., Inc. |             |              | VEHICLE TYPE<br><input type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |  |  |
| STREET ADDRESS<br>PO Box 368                       |             |              | VEHICLE MAKE<br>MODEL<br>3 R0688<br>YEAR<br>1999  |  |  |
| CITY<br>Cedar Falls                                | STATE<br>IA | ZIP<br>50613 | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br>1M2P267C8XM040014   |  |  |
| INSPECTOR'S NAME (Please Print)<br>Jon McConnell   |             |              | EMPLOYEE NO.<br>1   |  |  |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |    |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓  |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓  |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓  |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | ✓  |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓  |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓  |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |    |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |    |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |    |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | NA |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pin/Upper Plate     | ✓  |        | Tie-Downs         | ✓  |        | Sliders            | NA |        | <b>WINDSHIELD</b>     |    |        |
| Pintle-Hook/Eye     | ✓  |        | Headerboard       | ✓  |        |                    |    |        |                       | ✓  |        |
| Safety Chain(s)     | ✓  |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> |    |        |
|                     |    |        |                   |    |        |                    | ✓  |        |                       | ✓  |        |

## REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

Jon McConnell

DATE

12-2-13

APPLY LABEL TO A CLEAN, DRY SURFACE.  
USE WITH AN OVERLAMINATE (221-SN) TO  
IMPROVE DURABILITY UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

D9585333

# RECORD OF ANNUAL INSPECTION

(49 CFR, 396. 17-23)

Prepare Separate Report for Each Vehicle Inspected

DATE

12-17-15

D2236617

|   |  |  |  |  |                       |
|---|--|--|--|--|-----------------------|
| COMPANY NAME<br><b>Cedar Falls Construction Co., Inc.</b> |  |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER DOLLY |  |                       |
| STREET ADDRESS<br><b>PO Box 368</b>                       |  |  | VEHICLE MAKE<br><b>MACK</b>  |  | MODEL<br><b>RD600</b> |
| CITY STATE ZIP<br><b>Cedar Falls, IA 50613</b>            |  |  | YEAR<br><b>1999</b>  |  |                       |
| INSPECTOR'S NAME (Please Print)<br><b>Jon McConnell</b>   |  |  | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br><b>1M2P267C8XM040014</b>   |  |                       |
| EMPLOYEE NO.  |  |  |  |  |                       |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |    |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓  |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓  |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓  |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | NA |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓  |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓  |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |    |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |    |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |    |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | NA |        | Eqpt./Load Secure | ✓  |        | Attachments        | ✓  |        |                       |    |        |
| Pin/Upper Plate     | NA |        | Tie-Downs         | ✓  |        | Sliders            | NA |        | <b>WINDSHIELD</b>     | ✓  |        |
| Pintle-Hook/Eye     | ✓  |        | Headerboard       | ✓  |        |                    |    |        |                       |    |        |
| Safety Chain(s)     | ✓  |        | Other             |    |        | <b>MIRRORS</b>     | ✓  |        | <b>WINDSHLD. WIP.</b> | ✓  |        |
|                     |    |        |                   |    |        |                    |    |        |                       |    |        |

### REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

*Jon McConnell*

DATE

12-17-15

**APPLY LABEL TO A CLEAN, DRY SURFACE. USE WITH AN OVERLAMINATE (2402) TO IMPROVE DURABILITY UNDER NORMAL WEATHER CONDITIONS.**

**AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.**

D2236617

# RECORD OF ANNUAL INSPECTION

(49 CFR, 396. 17-23)

Prepare Separate Report for Each Vehicle Inspected

DATE

12-19-16

02236696

|  |  |  |                       |
|--|--|--|-----------------------|
| COMPANY NAME<br><b>Cedar Falls Construction Co., Inc.</b>                              |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |                       |
| STREET ADDRESS<br><b>PO Box 368</b>  |  | VEHICLE MAKE<br><b>MACK</b>  | MODEL<br><b>RD688</b> |
| CITY<br><b>Cedar Falls, IA 50613</b>   |  | YEAR<br><b>1999</b>  |                       |
| STATE<br><b>IA</b>   |  | ZIP<br><b>50613</b>  |                       |
| INSPECTOR'S NAME (Please Print)<br><b>Jon McConner</b>                                 |  | EMPLOYEE NO.   |                       |
| VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br><b>IM2P267C8XM040014</b> |  |  |                       |

## REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |    |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓  |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓  |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Low Air Warning     | ✓  |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Trailer Air Supply  | NA |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Compressor          | ✓  |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Other                 |    |        |
| Parking Brakes      | ✓  |        | Other             |    |        | Lines              | ✓  |        |                       |    |        |
| Other               |    |        |                   |    |        |                    |    |        | <b>WHEELS/RIM</b>     |    |        |
|                     |    |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | Fasteners             | ✓  |        |
| <b>COUPLERS</b>     |    |        | Access            | ✓  |        | Springs            | ✓  |        | Disc/Spoke            | ✓  |        |
| Fifth-Wheel & Mount | NA |        | Eqpt./Load Secure | ✓  |        | Attachments        | NA |        |                       |    |        |
| Pin/Upper Plate     | NA |        | Tie-Downs         | ✓  |        | Sliders            | NA |        | <b>WINDSHIELD</b>     | ✓  |        |
| Pintle-Hook/Eye     | ✓  |        | Headerboard       | ✓  |        |                    |    |        |                       |    |        |
| Safety Chain(s)     | ✓  |        | Other             |    |        | <b>MIRRORS</b>     |    |        | <b>WINDSHLD. WIP.</b> | ✓  |        |
|                     |    |        |                   |    |        |                    | ✓  |        |                       |    |        |

### REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE \_\_\_\_\_

Jon McConner

DATE \_\_\_\_\_

12-19-16

**APPLY LABEL TO A CLEAN, DRY SURFACE. USE WITH AN OVERLAMINATE (2402) TO IMPROVE DURABILITY UNDER NORMAL WEATHER CONDITIONS.**

**AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.**

02236696

DATE

**RECORD OF ANNUAL INSPECTION**

(49 CFR, 396. 17-23)

Prepare Separate Report for Each Vehicle Inspected

D5439626

|  |  |  |  |              |   |
|--|--|--|--|--------------|---|
| COMPANY NAME<br>CEDAR FALLS CONSTRUCTION       |  |  | VEHICLE TYPE<br><input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER<br><input type="checkbox"/> DOLLY |              |   |
| STREET ADDRESS<br>P O BOX 368                  |  |  | VEHICLE MAKE<br>MACK   |              | MODEL<br>RD688  |
| CITY<br>CEDAR FALLS, IA                        |  |  | STATE<br>50613   | YEAR<br>1997 | VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)<br>1M2P26768XM040014 |
| INSPECTOR'S NAME (Please Print)<br>GAVIN ALLEN |  |  |  | EMPLOYEE NO. |   |

**REPORT OF CONDITION** (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

|                     | OK | REPAIR |                   | OK | REPAIR |                    | OK | REPAIR |                       | OK | REPAIR |
|---------------------|----|--------|-------------------|----|--------|--------------------|----|--------|-----------------------|----|--------|
| <b>BRAKES</b>       |    |        | <b>EXHAUST</b>    |    |        | <b>STEERING</b>    |    |        | <b>FRAME</b>          |    |        |
| Adjustment          | ✓  |        | Leaks             | ✓  |        | Adjustment         | ✓  |        | Members               | ✓  |        |
| Mechan. Compon.     | ✓  |        | Placement         | ✓  |        | Column/Gear        | ✓  |        | Clearance             | ✓  |        |
| Drum/Rotor          | ✓  |        | <b>LIGHTING</b>   |    |        | Axle               | ✓  |        |                       |    |        |
| Hose/Tubing         | ✓  |        | Headlights        | ✓  |        | Linkage            | ✓  |        | <b>TIRES</b>          |    |        |
| Lining              | ✓  |        | Tail/Stop         | ✓  |        | Power Steering     | ✓  |        | Tread                 | ✓  |        |
| Antilock System     | ✓  |        | Clearance/Marker  | ✓  |        | Other              |    |        | Inflation             | ✓  |        |
| Automatic Adjusters | ✓  |        | Identification    | ✓  |        | <b>FUEL SYSTEM</b> |    |        | Damage                | ✓  |        |
| Low Air Warning     | ✓  |        | Reflectors        | ✓  |        | Tank(s)            | ✓  |        | Speed Restrictions    | NA |        |
| Trailer Air Supply  | NA |        | Other             |    |        | Lines              | ✓  |        | Other                 |    |        |
| Compressor          | ✓  |        |                   |    |        |                    |    |        |                       |    |        |
| Parking Brakes      | ✓  |        | <b>CAB/BODY</b>   |    |        | <b>SUSPENSION</b>  |    |        | <b>WHEELS/RIM</b>     |    |        |
| Other               |    |        | Access            | ✓  |        | Springs            | ✓  |        | Fasteners             | ✓  |        |
|                     |    |        | Eqpt./Load Secure | ✓  |        | Attachments        | NA |        | Disc/Spoke            | ✓  |        |
| <b>COUPLERS</b>     |    |        | Tie-Downs         | ✓  |        | Sliders            |    |        |                       |    |        |
| Fifth-Wheel & Mount | NA |        | Headerboard       | ✓  |        |                    |    |        | <b>WINDSHIELD</b>     | ✓  |        |
| Pin/Upper Plate     | NA |        | Motorcoach Seats  | NA |        | <b>MIRRORS</b>     |    |        |                       |    |        |
| Pintle-Hook/Eye     | ✓  |        | Other             |    |        |                    |    |        | <b>WINDSHLD. WIP.</b> | ✓  |        |
| Safety Chain(s)     | ✓  |        |                   |    |        |                    |    |        |                       |    |        |

## REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

DATE

12-13-19

APPLY LABEL TO A CLEAN, DRY SURFACE.  
USE WITH AN OVERLAMINATE (2402) TO  
IMPROVE DURABILITY UNDER NORMAL  
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED  
FOR USE WHEN FILLING OUT THE LABEL.  
INDELIBLE INK IS PERMANENT AND WILL NOT  
WASH OFF, BUT MAY FADE DUE TO EXPOSURE  
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL  
DISCRETION IS ADVISED REGARDING  
APPLICATION OF LABEL TO AN AREA NOT  
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT  
AND/OR ELEMENTS AND IT IS RECOMMENDED  
THAT THE READABILITY OF THE LABEL BE  
CHECKED PERIODICALLY.

12 2019  
#33

D5439626

1M2P26768XM040014