


I got
this when
we bought
the farm



NOV 1904
I got this when we bought the farm

NAME _____

Section _____ Township _____ County _____

Contractor Boards Inc Date Installed 10-10-83

Amount of Tile Installed: 5" 2675 6" 1400 8" _____

4" 18790 10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.


THE SHEFFIELD BRICK & TILE COMPANY, SHEFFIELD, IOWA 50475

I got this when we bought the farm

425 5962

North


Fullerton Did
in 2010



Customer: Kevin Smith		
Location: Fischer Farm		
Scale: 350 feet	Spacing:	Date: 11/2010
Fullerton Excavating		

— 4 in: 5147 ft

Tried to
put
one
Sheet



NAME
W
O TILE RECORD MAP
NO 11 101 1000
PLAN OF TILE SYSTEM
Hogs

Scale