Item#	Lot #	Serial #	Make	Model
14891		4V4NC9EG8N278852	Volvo	VNL
Cab	Good	Fair	Bad	Operational
Seat	X	raii	Dau	Operational
Horn	X			Х
Warning Lights	X			X
Clean	X			, A
Glass	X			
AC	Х			
Heater	X			Х
Mileage	230184			
Hours				
Transmission	Automatic			Х
Dash Lights				Х
Gauges				Х
Seat Belts				Х
Overall Condition	Х			
Front Axle Weight	12,349			
Rear Axle Weight	38,000			
GVWR	50,350			

Exterior	Good	Fair	Bad	Size / Capacity
Axles	Х			
Front Tires	Х			275/80R22.5
Rear Tires				295/75R22.5
Rims	х			
Lug Nuts	X			
Frame	X			
Paint	X			
Sheet Metal	X			
Fiberglass	X			
Mirrors	Х			
Fuel Tanks	х			
Bed				
Tailgate				
Transfer Case				
Lights	Х			
4 X 2				
4 X 4				
4 X 6	Х			

Engine	Yes	No	Missing	Operational
Blow By		Х		
Turbo	Х			Х
Radiator	Х			Х
Oil Leaks		Х		
Water Leaks		Х		
Belts	Х			
Emissions Label	Х			
Exhaust	Х			

Drive Train	Operational	l	Nonoperational
Transmission	х		
Front Axle			
Rear Axle	Х		
Rear Axle	х		
Transfer Case			

Logistics	
Front	12,349
Rear	38,000
GVWR	50,350