



We Strengthen Your Business

Item #	Lot #	Serial #	Make	Model	Year
14912	5106	43001328	Tennant	ATLV-4300	
Cab	Good	Fair	Bad	Operational	
Seat	X				
Horn			X		
Warning Light	X			X	
Clean	X				
Glass	N/A				
AC	N/A			X	
Heater	X			X	
Mileage	N/A				
Hours	563				
Transmission	Hydrosttic			X	
Dash Lights	X			X	
Gauges	X			X	
Seat Belts	X			X	
Overall Condit	X				
Brakes	Hydrosttic				
Cab Type	OPEN				
Exterior	Good	Fair	Bad	Size / Capacity	
Axles	X				
Front Tires	X				
Rear Tires	X				
Rims	X				
Lug Nuts	X				
Frame	X				
Paint	X				
Sheet Metal	X				
Fiberglass	N/A				
Mirrors	N/A				
Fuel Tanks	X				
Lift Arms	N/A				
Pins / Bushing	X				
4 X 2	N/A				
4 X 4	X				
Vac System					
Gutter Broom					
Comment	Vac System was not operational checked				

Engine	Yes	No	Missing	Operational
Blow By		X		
Turbo		X		
Radiator	X			
Oil Leaks		X		
Water Leaks		X		
Belts	X			
Emissions Label		X		
Exhaust	X			
Engine Type	Kubota			
Engine Model	3 Cylinder			
Fuel Type	Diesel			

Drive Train	Operational	Nonoperational
Transmission	X	
Front Axle	X	
Rear Axle	N/A	
Rear Axle	X	
Transfer Case	X	

Logistics	
Length	12'
Width	55"
Height	7'