

**EQUIFY AUCTIONS INSPECTION REPORT**

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
19545	John Deere	328	2005	T00328B100811

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	X				Tracks	N/A			
Horn	X				Tires / Lugs	X			14-17.5
Warning Lights	X				Sprockets	N/A			
Clean	X				Idlers	N/A			
Glass	X				Bushings	N/A			
AC	N/A				Blade	N/A			
Heater	N/A				Frame	X			
Mileage	N/A				Paint	X			
Hours	4,543				Sheet Metal	X			
Transmission	X			X	Fiberglass	X			
Dash Lights	X			X	Mirrors	X			
Gauges	X			X	Fuel Tanks	X			
Seat Belts	X			X	Bucket	Smooth			84"
Overall Condition	X				Lights	X			
Cab Type	OPEN				Hyd. Tank	X			
					Hoses	X			
					Cutting Edge	X			
					Coupler	MANUAL			
					Forks	46"			
Comments					Comments	Unit will not stay running;			
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	N/A				Drive Motors	HYDROSTATIC			
Turbo	N/A								
Radiator	X								
Oil Leaks		X							
Water Leaks		X							
Belts	X			X					
Emissions Label		X							
Exhaust	X			X					
Engine Type	Diesel			X					
Engine Model	4 Cylinder			X					
Engine Make	John Deere								
Comments					Comments				
LOGISTICS					MISC.				
Length	13'								
Width	84"								
Height	7'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.