

**EQUIFY AUCTIONS INSPECTION REPORT**

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
19946	Kenworth	W-900	2006	1XKWDBOX57J167972

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	X				Axles	X			
Horn	X				Front Tires	X			11R22.5
Warning Lights	X				Rear Tires	X			11R22.5
Clean	X				Rims	X			
Glass	X				Lug Nuts	X			
A/C Heater	X				Frame	X			
Mileage	398,472				Paint	X			
Hours	N/A				Sheet Metal	X			
Transmission	Eaton Fuller 18				Fiberglass	X			
Dash Lights	x				Mirrors	X			
Gauges	x				Fuel Tanks	X			
Seat Belts	x				Bed	N/A			
Overall Condition	x	X			Tailgate	N/A			
Brakes	X				Transfer Case	N/A			
Sleeper Size	N/A				Air Ride Cab	N/A			
Front Axle Weight	13,200				Lights	X			
Rear Axle Weight	46,000				4 X 2	N/A			
GVWR	59,200				4 X 4	N/A			
Sun Roof	NO				4 X 6	X			
Cab Size	Day				5Th Wheel	Fixed			
Cruise	Yes				Air Ride Cab	X			
Wheel Base	224"								
Engine Brake	X								
Air Ride Seat	X								
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By		X			Transmission	X		X	
Turbo	x				Front Axle	X			
Radiator	X				Rear Axle	X			
Oil Leaks	X				Rear Axle	X			
Water Leaks		X			Transfer Case	N/A			
Belts	X				Front Suspension	SPRING			
Emissions Label		X			Rear Suspension	SPRING			
Exhaust	X								
Fuel Type	Diesel								
Engine Model	C-15								
Engine Make	CAT								
Comments					Comments				
LOGISTICS					MISC.	Good	Fair	Poor	
Length	24'				PTO	X			
Width	102"								
Height	12'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.