

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20180	Mack	RD688S	1996	1M2P267C8TM025863

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	X				Axles	X			
Horn	X			x	Front Tires	X			LT215/85R16
Warning Lights	X			x	Rear Tires	X			LT215/85R16
Clean	X				Rims	X			
Glass	X				Lug Nuts	X			
A/C Heater	X				Frame	X			
Mileage	488,297			x	Paint	x			
Hours	32,405				Sheet Metal	x			
Transmission	Eaton Fuller			8LL	Fiberglass	X			
Dash Lights	x			x	Mirrors	X			
Gauges	x			x	Fuel Tanks	X			
Seat Belts	x			x	Bed	Dump 21'			
Overall Condition	X				Tailgate	X			
Brakes	X				Transfer Case	N/A			
Sleeper Size	N/A				Air Ride Cab	Yes			
Front Axle Weight	18,000				Lights	X			
Rear Axle Weight	38,000				4 X 2	N/A			
GVWR	69,000				4 X 4	N/A			
Sun Roof	NO				4 X 6	X			
Cab Type	DAY				5Th Wheel	N/A			
Cruise	Yes				PTO	X			
Wheel Base	X				Hyd. Tank	Yes			
Engine Brake	X				Tarp	Electric			
Air Ride Seat	X								
Air Brakes	X								
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By		X			Transmission	X			
Turbo		X			Front Axle	X			
Radiator	X				Middle Axle	X			
Oil Leaks		X			Rear Axle	X			
Water Leaks		X			Transfer Case	N/A			
Belts	X				Front Suspension	SPRING			
Emissions Label	X				Rear Suspension	Camel Back			
Exhaust	X								
Fuel Type	GAS								
Engine Model	V-8								
Engine Make	VORTEC								
Comments					Comments				
LOGISTICS					MISC.	Good	Fair	Poor	
Length	33'				3 Steerable Drop Axles	X			
Width	102"								
Height	11'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.