

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20239	MACK	CL713	1998	1M2AD62Y8WW006046

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	X				Axles	X			
Horn	X			x	Front Tires	X			385/65r22.5
Warning Lights	N/A			x	Rear Tires	X			11r22.5
Clean	N/A				Rims	X			
Glass	X				Lug Nuts	X			
A/C Heater	X				Frame	X			
Mileage	9,160			x	Paint	x			
Hours	N/A				Sheet Metal	x			
Transmission	MACK 13			x	Fiberglass	X			
Dash Lights	x			x	Mirrors	X			
Gauges	x			x	Fuel Tanks	X			
Seat Belts	x			x	Bed	N/A			
Overall Condition		X			Tailgate	N/A			
Brakes	X				Transfer Case	N/A			
Sleeper Size	N/A				Air Ride Cab	yes			
Front Axle Weight	N/A				Lights	X			
Rear Axle Weight	N/A				4 X 2	N/A			
GVWR	N/A				4 X 4	N/A			
Sun Roof	NO				4 X 6	x			
Cab Type	DAY				5Th Wheel	Slider			
Cruise	Yes								
Wheel Base	170"								
Engine Brake	x								
Air Ride Seat	x								
Air Brakes	x								
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	X				Transmission	X			
Turbo	X				Front Axle	X			
Radiator	X				Middle Axle	X			
Oil Leaks		X			Rear Axle	X			
Water Leaks		X			Transfer Case	N/A			
Belts	X				Front Suspension	SPRING			
Emissions Label	X				Rear Suspension	AIR			
Exhaust	X								
Fuel Type	DIESEL								
Engine Model	E7								
Engine Make	MACK								
Comments					Comments				
LOGISTICS					MISC.	Good	Fair	Poor	
Length	23'				PTO	x			
Width	108"								
Height	11'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.