

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20311	Ford	F-450	2008	1FDXX46R48ED15465

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	X				Axles	X			
Horn	X				Front Tires	X			225/70R19.5
Warning Lights	X				Rear Tires	X			225/70R19.5
Clean	X				Rims	X			
Glass	X				Lug Nuts	X			
A/C Heater	X				Frame	X			
Mileage	188,530				Paint	X			
Hours	N/A				Sheet Metal	X			
Transmission	Automatic				Fiberglass	X			
Dash Lights	x				Mirrors	X			
Gauges	x				Fuel Tanks	X			
Seat Belts	x				Bed	N/A			
Overall Condition	x				Tailgate	N/A			
Brakes	X				Transfer Case	N/A			
Sleeper Size	N/A				Air Ride Cab	N/A			
Front Axle Weight	5,600				Lights	X			
Rear Axle Weight	12,000				4 X 2	X			
GVWR	16,000				4 X 4	N/A			
Sun Roof	NO				4 X 6	N/A			
Cab Size	Extra Cab				5Th Wheel	N/A			
Cruise	Yes				Air Ride Cab	N/A			
Wheel Base	162"								
Engine Brake	N/A								
Air Ride Seat	N/A								
Eng. Brake	N/A								
Mirrors	N/A								
Comments	Power Locks,Windows, Mirrors, Running Boards				Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By		X			Transmission	X		X	
Turbo	x				Front Axle	X			
Radiator	X				Rear Axle	N/A			
Oil Leaks	X				Rear Axle	X			
Water Leaks		X			Transfer Case	N/A			
Belts	X				Front Suspension	SPRING			
Emissions Label		X			Rear Suspension	Spring			
Exhaust	X								
Fuel Type	Diesel								
Engine Model	ISX435ST								
Engine Make	Cummins								
Comments					Comments	Inside duel tires are missing			
LOGISTICS					MISC.	Good	Fair	Poor	
Length	22'				Service Body				
Width	102"								
Height	9'5"								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.