

Item #	Lot #	Serial #	Make	Model
47217	110	W004X2X034010	John Deere	Gator
Cab	Good	Fair	Bad	Operational
Seat		X		
Horn				
Warning Lights				
Clean	X			
Glass				
AC				
Heater				
Mileage	1100			
Hours				
Transmission	Hydrostatic			X
Dash Lights				
Gauges				
Seat Belts				X
Overall Condition	X			
Front Axle Weight				
Rear Axle Weight				
GVWR				

Exterior	Good	Fair	Bad	Size / Capacity
Axles				
Front Tires	X			
Rear Tires	x			
Rims	x			
Lug Nuts	X			
Frame	X			
Paint	X			
Sheet Metal	X			
Fiberglass	X			
Mirrors	N/A			
Fuel Tanks	X			
Bed	X			
Tailgate	x			
Transfer Case	N/A			
Lights	X			
4 X 2	x			
4 X 4	N/A			
4 X 6	N/A			

Engine	Yes	No	Missing	Operational
Blow By		X		
Turbo				
Radiator				
Oil Leaks		X		
Water Leaks		X		
Belts	X			
Emissions Label				
Exhaust	X			

Drive Train	Operational		Nonoperational
Transmission	X		
Front Axle	N/A		
Rear Axle	X		
Rear Axle	N/A		
Transfer Case	N/A		

Logistics	
Length	8'
Width	60"
Height	4'