

EQUIFY AUCTIONS INSPECTION REPORT

| ITEM NUMBER | MAKE | MODEL | YEAR | SERIAL NUMBER |
|-------------|------|--------|------|---------------|
| 65272 | CASE | 580 SL | | JJG0203423 |

| CAB | GOOD | FAIR | BAD | OPERATIONAL | EXTERIOR | GOOD | FAIR | BAD | SIZE/CAPACITY |
|-------------------|------------|-----------|----------------|--------------------|--------------------|--------------------|------------------------|-----|---------------|
| Seat | X | | | | Axles | X | | | |
| Horn | X | | | | Front Tires | | X | | 12-16.5 |
| Warning Lights | X | | | | Rear Tires | | X | | 19.5L |
| Clean | X | | | | Rims | X | | | |
| Glass | X | | | | Lug Nuts | X | | | |
| AC | N/A | | | | Frame | X | | | |
| Heater | X | | | | Paint | X | | | |
| Mileage | N/A | | | | Sheet Metal | X | | | |
| Hours | 3959 | | | | Fiberglass | X | | | |
| Transmission | X | | | X | Mirrors | X | | | |
| Dash Lights | X | | | X | Fuel Tanks | X | | | |
| Gauges | X | | | X | Lift Arms | X | | | |
| Seat Belts | X | | | X | Pins / Bushings | X | | | |
| Overall Condition | X | | | | Extenda Stick | Yes | | | |
| Brakes | X | | | X | Stick | N/A | | | |
| Cab Type | CLOSED | | | | 4 X 2 | N/A | | | |
| | | | | | 4 X 4 | X | | | |
| | | | | | Front Bucket | 83" | | | |
| | | | | | Rear Bucket | 18" | | | |
| | | | | | Out Riggers | Street Pads | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Comments | | | | | Comments | | | | |
| | | | | | | | | | |
| ENGINE | YES | NO | MISSING | OPERATIONAL | DRIVE TRAIN | OPERATIONAL | NON-OPERATIONAL | | |
| Blow By | X | | | | Transmission | X | | | |
| Turbo | X | | | | Front Axle | X | | | |
| Radiator | X | | | | Rear Axle | N/A | | | |
| Oil Leaks | | X | | | Rear Axle | X | | | |
| Water Leaks | | X | | | Transfer Case | X | | | |
| Belts | X | | | | | | | | |
| Emissions Label | | X | | | | | | | |
| Exhaust | X | | | | | | | | |
| Fuel Type | Diesel | | | | | | | | |
| Engine Model | 4T-390 | | | | | | | | |
| Engine Make | Case | | | | | | | | |
| | | | | | | | | | |
| Comments | | | | | Comments | | | | |
| | | | | | | | | | |
| LOGISTICS | | | | | MISC. | | | | |
| Length | 26' | | | | | | | | |
| Width | 84" | | | | | | | | |
| Height | 10' | | | | | | | | |
| | | | | | | | | | |



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.