

Item #	Lot #	Serial #	Make	Model	Year
88930	410	JJGC232162	Case	580L	
Cab	Good	Fair	Bad	Operational	Engine
Seat	X				Blow By
Horn	X			X	Turbo
Warning Lights	X			X	Radiator
Clean		X			Oil Leaks
Glass	X				Water Leaks
AC	X			X	Belts
Heater	X			X	Emissions Label
Mileage	N/A				Exhaust
Hours	4521				
Transmission	4 Speed			X	
Dash Lights				X	
Gauges				X	
Seat Belts				X	
Overall Condition	X				
Brakes	Hydraulic				
Cab Type	Closed				
Exterior	Good	Fair	Bad	Size / Capacity	Drive Train
Axles	X				Transmission
Front Tires	X			11L-16	Front Axle
Rear Tires	X			24-19.5L	Rear Axle
Rims	X				Rear Axle
Lug Nuts	X				Transfer Case
Frame	X				
Paint	X				
Sheet Metal	X				
Fiberglass	X				
Mirrors	X				
Fuel Tanks	X				Logistics
Lift Arms	X				Length
Pins / Bushings	X				Width
Transfer Case	N/A				Height
Extenda Stick	N/A				
Stick	Standard				
4 X 2	X				
4 X 4	N/A				
Front Bucket	X			82"	
Rear Bucket	X			21"	

Yes	No	Missing	Operational
	X		
X			
X			
	X		
	X		
X			
	X		
X			

Operational		Nonoperational
X		
N/A		
Xn/a		
X		
N/A		

26'
82''
9'