

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
89098	Mack	CX613	2002	1M1AE06Y62W013354

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY	
Seat	X				Axles	X				
Horn	X			x	Front Tires	X			275/80R24.5	
Warning Lights	X			x	Rear Tires	X			275/80R24.5	
Clean	X				Rims	X				
Glass	X				Lug Nuts	X				
A/C Heater	X			x	Frame	X				
Mileage	875,729			x	Paint	X				
Hours	N/A				Sheet Metal	X				
Transmission	Meritor 10			x	Fiberglass	X				
Dash Lights	x			x	Mirrors	X				
Gauges	x			x	Fuel Tanks	X				
Seat Belts	x			x	Bed	N/A				
Overall Condition	x				Tailgate	N/A				
Brakes	X				Transfer Case	N/A				
Sleeper Size	x			36"	Air Ride Cab	x				
Front Axle Weight	12,000				Lights	X				
Rear Axle Weight	40,000				4 X 2	N/A				
GVWR	52,000				4 X 4	N/A				
Sun Roof	NO				4 X 6	x				
Cab Type	Sleeper				5Th Wheel	Slider				
Cruise	Yes				Air Ride Cab	x				
Wheel Base	224									
Engine Brake	x									
Air Ride Seat	x									
Air Brakes	x									
Comments					Comments					
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL			
Blow By		X			Transmission	X		X		
Turbo		x			Front Axle	X				
Radiator	X				Middle Axle	X				
Oil Leaks	X				Rear Axle	X				
Water Leaks		X			Transfer Case	N/A				
Belts	X				Front Suspension	SPRING				
Emissions Label		X			Rear Suspension	Air Ride				
Exhaust	X									
Fuel Type	Gas									
Engine Model	5.4L									
Engine Make	Ford									
Comments					Comments					
LOGISTICS					MISC.	Good	Fair	Poor		
Length	20'				PTO	x				
Width	102"									
Height	11'									



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.