

**EQUIFY AUCTIONS INSPECTION REPORT**

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
19164 or 14951	hpsi			H79093RP

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat		X			Axles	N/A			
Horn	N/A				Front Tires	N/A			
Warning Lights	N/A				Rear Tires	N/A			
Clean		X			Rims	N/A			
Glass	N/A				Lug Nuts	N/A			
AC	N/A				Frame		X		
Heater	X				Paint	X			
Mileage	N/A				Sheet Metal	X			
Hours	1377				Fiberglass	X			
Transmission	N/A				Mirrors	N/A			
Dash Lights	X				Fuel Tanks	X			
Gauges	X				Lift Arms	X			
Seat Belts	N/A				Pins / Bushings	X			
Overall Condition		X			Extenda Stick	N/A			
Brakes	Hydrostatic				Stick	N/A			
Cab Type	Closed				4 X 2	N/A			
Drive Motors	X				4 X 4	N/A			
					Front Bucket	N/A			
					Rear Bucket	N/A			
					Out Riggers	x			
					Trench Bar	N/A			
					Boom	X			
					Drill Rod	6" x 32'			
					Hydraulic Tank	X			
					Hydraulic Hoses	LEAK			
Comments					Comment				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By		x			Transmission				
Turbo	x				Front Axle				
Radiator	x				Rear Axle				
Oil Leaks		x			Rear Axle				
Water Leaks		x			Transfer Case				
Belts	x								
Emissions Label		x							
Exhaust	x								
Engine Type	Catapillar								
Engine Model	3208								
Fuel Type	Diesel								
Comments					Comments				
LOGISTICS					MISC.				
Length	50'								
Width	113"								
Height	12'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.