

## EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20212	VOLVO	670 T/A	2011	4V4NC9EH1BN299671

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	X				Axles	X			
Horn	X			X	Front Tires	X			295/75R22.5
Warning Lights	X			X	Rear Tires	X			295/75R22.5
Clean	X				Rims	X			
Glass	X				Lug Nuts	X			
A/C Heater	X			X	Frame	X			
Mileage	910,091			X	Paint	X			
Hours	N/A				Sheet Metal	X			
Transmission	EATON FULLER 10			X	Fiberglass	X			
Dash Lights	X			X	Mirrors	X			
Gauges	X			X	Fuel Tanks	X			
Seat Belts	X			X	Bed	X			
Overall Condition	X				Tailgate	N/A			
Air Brakes	X			X	Transfer Case	N/A			
Sleeper Size	48"				Air Ride Cab	X			
Front Axle Weight	12,350				Lights	X			
Rear Axle Weight	38,000				4 X 2	N/A			
GVWR	50,350				4 X 4	N/A			
					4 X 6	X			
					5Th Wheel	SLIDER			
Comments					Comments				
<b>ENGINE</b>	<b>YES</b>	<b>NO</b>	<b>MISSING</b>	<b>OPERATIONAL</b>	<b>DRIVE TRAIN</b>	<b>OPERATIONAL</b>	<b>NON-OPERATIONAL</b>		
Blow By		X			Transmission	X	No Reverse		
Turbo		X			Front Axle	N/A			
Radiator	X				Rear Axle	X			
Oil Leaks		X			Rear Axle	X			
Water Leaks		X			Transfer Case	N/A			
Belts	X				Front Suspension	SPRING			
Emissions Label	X				Rear Suspension	AIR RIDE			
Exhaust	X								
Fuel Type	Diesel								
Engine Model	D13								
Engine Make	VOLVO								
Comments					Comments				
<b>LOGISTICS</b>					<b>MISC.</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>	
Length	26'				3300 Gallon Tank	X			
Width	102"				PTO Pump	X			
Height	13'				Jurop Vac. Pump	X			



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
[equifyauctions.com](http://equifyauctions.com)

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.