

## EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20223	INTERNATIONAL	PAYSTAR	2013	1HTXLSHT3J486145

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	Air				Axles	X			
Horn	X			X	Front Tires	X			11425/65R22.5
Warning Lights	X			X	Rear Tires	X			11R22.5
Clean	X				Rims	X			
Glass	X				Lug Nuts	X			
A/C Heater	X			X	Frame	X			
Mileage	23,913			X	Paint	X			
Hours	N/A				Sheet Metal	X			
Transmission	Eaton Fuller 9			X	Fiberglass	X			
Dash Lights	X			X	Mirrors	X			
Gauges	X			X	Fuel Tanks	X			
Seat Belts	X			X	Bed	N/A			
Overall Condition	X				Tailgate	N/A			
Air Brakes	x			X	Transfer Case	N/A			
Sleeper Size	N/A				Air Ride Cab	x			
Front Axle Weight	N/A				Lights	X			
Rear Axle Weight	N/A				4 X 2	N/A			
GVWR	60,000				4 X 4	N/A			
Wheel Base	248"				4 X 6	x			
Mirrors	Heated				5Th Wheel	N/A			
PTO	X			X	Drum	X			
locks	Manual			X	Chuts	3			4'
Windows	Power			X	Drum Rollers	X			
					Rear Controls	X			
Comments	CHECK ENG, OIL CHANGE LIGHT STAYSON.				Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By		X			Transmission	X			
Turbo		X			Front Axle	N/A			
Radiator	X				Rear Axle	x			
Oil Leaks		X			Rear Axle	X			
Water Leaks		X			Transfer Case	N/A			
Belts	X				Front Suspension	SPRING			
Emissions Label	X				Rear Suspension	Beam			
Exhaust	X								
Fuel Type	Diesel								
Engine Model	10.5L								
Engine Make	maxforce								
Comments					Comments				
LOGISTICS					MISC.	Good	Fair	Poor	
Length	34'				Continenal Mixer Body	X			11 Cubic Yards
Width	102"				Water Tank	X			125 Gallons
Height	13'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
[equifyauctions.com](http://equifyauctions.com)

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.