

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20228	CATERPILLAR	963		21Z04644

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Seat	X				Axles	N/A			
Horn	X				Front Tires	N/A			
Warning Lights	X				Rear Tires	N/A			
Clean	X				Rims	x			
Glass	X				Lug Nuts	x			
AC	N/A				Frame	X			
Heater	X				Paint	X			
Mileage	N/A				Sheet Metal	X			
Hours	2308+4881				Fiberglass	X			
Transmission	Power Shift			X	Mirrors	X			
Dash Lights	X			X	Fuel Tanks	X			
Gauges	X			X	Lift Arms	X			
Seat Belts	X			X	Pins / Bushings	X			
Overall Condition	X				Extenda Stick	N/A			
Brakes	X			X	Stick	N/A			
Cab Type	CLOSED				4 X 2	N/A			
					4 X 4	N/A			
					Front Bucket	99" Tooth Bucket			
					Rear Bucket	N/A			
					Out Riggers	N/A			
					Tracks	21.5			
					Sprockets	N/A			
					Bushings	N/A			
					Idelers	N/A			
					Ripper	3 Shank			
Comments	Doors are missing.				Comments	Shanks Missing			
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	X				Transmission	X			
Turbo	X				Front Axle	N/A			
Radiator	X				Rear Axle	N/A			
Oil Leaks		X			Rear Axle	N/A			
Water Leaks		X			Transfer Case	N/A			
Belts	X								
Emissions Label		X							
Exhaust	X								
Engine Type	DIESEL								
Engine Model	3304								
Engine Make	CATAPILLAR								
Comments					Comments				
LOGISTICS					MISC.				
Length	23'								
Width	99"								
Height	11'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.