EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE MODEL YEAR SERIAL NUMB		SERIAL NUMBER	
65246	Mack	CH11613	2015	1XKDD110X14106211

GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY	
Air				Axles	Х				
X			Х	Front Tires	Х			11R24.5	
X			Х	Rear Tires	Х			11R24.5	
X				Rims	Х				
X				Lug Nuts	Х				
X			Х	Frame	Х				
138,710			Х	Paint	Х				
N/A				Sheet Metal	Х				
EATON FULLER 1	13		Х	Fiberglass	Х				
Х			Х	Headace Rack	Х				
Х			х	Fuel Tanks	x				
x			х	Bed	N/A				
х				Tailgate	N/A				
х			Х	Transfer Case	N/A				
N/A				Air Ride Cab	Х				
14,320				Lights	Х				
44,000				4 X 2	N/A				
58,320				4 X 4	N/A				
212"				6 X 4	х				
Х			Х	5Th Wheel	Х				
Х			Х	Drum	N/A				
Manual			Х	Chuts	N/A				
Manual			Х	Drum Rollers	N/A				
х									
Х					Day				
Х				WET Kit	N/A				
	•			Comments	TRAILER DOES N	IOT COME WITH U	INIT		
YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	OPERATIONAL		NON-OPERATIONAL	
	Х			Transmission	х	X			
х				Front Axle	N/A	N/A			
х				Rear Axle	х	х			
	Х			Rear Axle	х	Α			
	Х			Transfer Case	N/A	N/A			
Х				Front Suspension	SPRING	SPRING			
Х				Rear Suspension	Camel Back	Camel Back			
Х									
Diesel									
MP8-415 12.8L									
CAT									
415									
		•	•	Comments			•		
•					•				
				MISC.	Good	Fair	Poor		
25'				DEF FLUID					
102''									
12'							İ		
		1				İ	Ì		
	 	+	+			—	1	1	
	Air X X X X X X X X X X X X X	Air X X X X X X X X X 138,710 N/A EATON FULLER 13 X X X X X X X X X X X X X	Air X X X X X X 138,710 N/A EATON FULLER 13 X X X X X X X X X X X X X	Air X X X X X X X X X X X X X	Air X X X X X X X X X X X X X	Air	Air	Air	



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050

equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable, as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.