

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20106	GMC	2500	2006	1GTHK23245F803050

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab	EXT.				Lights	OPERATIONAL			
Clean	Good				Front Tires	GOOD			LT265/7570R16
Warning Lights	Operational				Rear Tires	GOOD			LT265/7570R16
Horn	Operational				Rims / Lug Nuts	GOOD			
Glass	Good				Park Brake	GOOD			
A/C Heater	Operational				Frame	GOOD			
Mileage	274,406				Paint	GOOD			
Hours	N/A				Sheet Metal	GOOD			
PTO	N/A				Fiberglass	GOOD			
Dash Lights	Operational				Mirrors	GOOD			
Gauges	Operational				Fuel Tanks	GOOD			
Seat Belts	Operational				Bed	6'4"			
Controls	N/A				Tailgate	GOOD			
Air Brakes	N/A								
Sleeper Size	N/A				4 X 2	N/A			
Front Axle Weight	N/A				4 X 4	YES			
Rear Axle Weight	N/A				Sunroof	N/A			
GVWR	N/A				Rear Sliding Glass	N/A			
Seat	Good				Running Boards	YES			
Tilt	Yes				Bed Mat	N/A			
Telescope	N/A				Tool Box	N/A			
Window Controls	Operational				Bed liner	N/A			
Power Locks	Operational				Hitch	YES			
Power Mirrors	Operational				Fuel Transfer Tank	N/A			
Heated Mirrors	N/A				Wheel Base	N/A			
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By		X			Transmission	YES			
Turbo		X			Front Axle	GOOD			
Radiator	X				Rear Axle	GOOD			
Oil Leaks		X			Rear Axle	N/A			
Water Leaks		X			Transfer Case	GOOD			
Belts	X				Front Suspension	GOOD			
Emissions Label	X				Rear Suspension	GOOD			
Exhaust	X								
Engine Type	DIESEL								
Engine Model	6.6								
Engine Make	DURAMAX								
Overall Condition	GOOD				Overall Condition	GOOD			
Comments					Comments				
LOGISTICS					MISC.				
Length									
Width									
Height									



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.