

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20116	FREIGHTLINER		1994	1FUVDZYB5RH864986

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	SLEEPER 48"				Front Tires	X			11R24.5
Clean		X			Rear Tires	X			11R24.5
Seat		X			Rims	X			
Seat Belts	X				Lug Nuts	X			
Air Ride Seat	YES				Wheel Base	221"			
Brake Type	AIR				Paint		X		
Warning Lights	X				Sheet Metal			Minor Dents	
Guages	X				Fiberglass			Cracks	
Mileage	137797				Mirrors	X			
Hours	N/A				Fuel Tanks	X			
Horn	X				Bed	N/A			
Glass	X				Tailgate	N/A			
Cruise	X				Transfer Case	N/A			
Brakes	AIR				Air Ride Cab	yes			
Engine Brake	X				Lights	X			
Sleeper Size	N/A				5Th Wheel	Slider			
Front Axle Weight	12,000				PTO	X			
Rear Axle Weight	38,000				Hyd. Tank	X			
GVWR	50,000				Tarp	MANUAL			
Sun Roof	N/A				Headace Rack	N/A			
Door Controls	X				Wet Kit	N/A			
Heated Mirrors	N/A				Frame	X			
Rear Sliding Glass	N/A				Overall Condition		X		
Overall Condition		X							
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	x				Transmission	Rockwell 9 Speed			
Turbo	x				Front Axle	x			
Radiator	x				Middle Axle	x			
Oil Leaks		x			Rear Axle	x			
Water Leaks		x			Transfer Case	N/A			
Belts	x				Front Suspension	Spring			
Emissions Label		x			Rear Suspension	Air			
Exhaust	x				4 X 2	N/A			
Fuel Type	Diesel				4 X 4	N/A			
Engine Model	60 Series				4 X 6	x			
Engine Make	Detroit				Overall Condition	Good			
A/C Compressor	x								
Overall Condition	Good				Comments				
Comments									
LOGISTICS					MISC.	Good	Fair	Poor	
Length	25'								
Width	102"								
Height	12'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.