EQUIFY AUCTIONS	INSPECTION	REPORT							
ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMB	ER				
20123	Ranco	Bottom Dump	1992	Data Plate Is Missing					
BED	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Useable deck	N/A		5,15	0. 2.0.0.0.0.2	EALENION	0000		5715	0.22, 0.1. / 0.1.
Upper Deck	N/A								
Rear Deck	N/A								
Connections	GOOD								
Hitch	GOOD								
D Rings	N/A								
Tie Downs	N/A								
Frame	GOOD								
Lights	X								
Tank	N/A								
Baffales	N/A								
Jeep	N/A								
Stinger	N/A						. / .		
Paint	X					r	I/A		
Metal	х								
Hydraulics	N/A								
Dove Tail	N/A								
Ramps	N/A								
Suspensions	Spring								
GVWR	N/A								
Tires	11R24.5								
Air Brakes	Good								
Overall Condition	х								
comments				Comments					
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL		NON-OPERATIO	ΝΔΙ
Blow By	N/A			0. 2.0.0.0.0.2		012101101012			
Turbo	N/A								
Radiator	N/A								
Oil Leaks	N/A								
Water Leaks	N/A								
Belts	N/A								
Emissions Label	N/A					1	I/A		
Exhaust	N/A								
Overall Condition	N/A								
Comments					Comments				
LOGISTICS					MISC.				
Length	42'				Manual Tarp			1	
Width	102"				Push Block				
Height	10'								
								1	
							1		



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050

equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable, as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report. All this inspection was performed.