

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20124	Road DP	Bottom Dump	1992	4SBG54224XS100281

BED	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Useable deck	N/A				N/A				
Upper Deck	N/A								
Rear Deck	N/A								
Connections	GOOD								
Hitch	GOOD								
D Rings	N/A								
Tie Downs	N/A								
Frame	GOOD								
Lights	X								
Tank	N/A								
Baffles	N/A								
Jeep	N/A								
Stinger	N/A								
Paint	X								
Metal	X								
Hydraulics	N/A								
Dove Tail	N/A								
Ramps	N/A								
Suspensions	Spring								
GVWR	60,000								
Tires	11R24.5								
Air Brakes	Good								
Overall Condition	X								
Comments									
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	N/A				N/A				
Turbo	N/A								
Radiator	N/A								
Oil Leaks	N/A								
Water Leaks	N/A								
Belts	N/A								
Emissions Label	N/A								
Exhaust	N/A								
Overall Condition	N/A								
Comments									
LOGISTICS					MISC.				
Length	42'				Manual Tarp				
Width	102"				Push Block				
Height	10'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.