## **EQUIFY AUCTIONS INSPECTION REPORT**

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20128	Nuttall	Drop Deck	1980	NMC225FXX03750449

BED	GOOD	FAIR	BAD	OPERATIONAL	EVT	EDIOD	ERIOR GOOD	ERIOR GOOD FAIR	ERIOR GOOD FAIR BAD
Useable deck	23'	FAIR	DAU	OPERATIONAL		EXTERIOR	EXTERIOR	EXTERIOR GOOD FAIR	EXTERIOR GOOD FAIR DAD
		_							
Upper Deck	N/A	_			l				
Rear Deck	N/A	_			l				
Connections	GOOD								
Hitch	GOOD	_			l				
D Rings	10								
Tie Downs	N/A								
Frame	GOOD								
Lights	X								
Tank	N/A								
Baffales	N/A								
Jeep	N/A								
Stinger	N/A								
aint	X				1		- I	N/A	N/A
Лetal	X				1		-	<del>-</del>	<del>-</del>
Hydraulics	N/A				1	•	1		
Dove Tail	3'				ĺ				
	N/A	-			l				
Ramps		_							
Suspensions	Spring	_							
GVWR	50,000	_							
Tires	9R17.5								
Air Brakes	Good				ı	1			
Overall Condition	X				l				
					l				
					1				
					l				
Comments						Comments	Comments	Comments	Comments
					l				
IGINE	YES	YES NO MISSING OPERATIONA		OPERATIONAL	Ī	DRIVE TRAIN	DRIVE TRAIN OPERATIONAL	DRIVE TRAIN OPERATIONAL	DRIVE TRAIN OPERATIONAL NON-OPER
Blow By	N/A				l				
Turbo	N/A				l				
Radiator	N/A								
Oil Leaks	N/A				ı	1			
Water Leaks	N/A	-							
		_							
Belts	N/A	_						N/A	A1/A
Emissions Label	N/A				l		N	N/A	N/A
Exhaust	N/A				l				
Overall Condition	N/A				l				
					l				
Comments						Comments	Comments	Comments	Comments
						Commence	Comments	Comments	Comments
LOGISTICS					I	MISC.	MICC	MICC	MICC
	401				I	Misc.	MISC.	MISC.	IVIISC.
Length	40'	+	+		I				
Width	96"				I				
Height	5'				l				
					1				
					п				



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050

equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable, as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.