EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20135	Caterpillar	D6D	1983	4X5743

CAB	GOOD	FAIR	BAD	OPERATIONAL
Cab Type	Closed			
Clean	X			
Seat	X			
Seat Belts	X			
Air Ride Seat	N/A			
Brake Type	X			
Warning Lights	N/A			
Guages	X			
Mileage	N/A			
Hours	11749			
Horn			Does Not Work	
Glass		Cracked		
Controls	X			
Brakes	X			
Door Controls	X			
Heated Mirrors	N/A			
Lights	X			
Steering	Lever			
Overall Condition	Good			
Comments				

EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Frame	X			
Paint	X			
Sheet Metal	Minor Dents			
Fiberglass	N/A			
Mirrors	N/A			
Fuel Tanks	X			
Bucket	N/A			
Wench	yes			
Ripper	N/A			
Screens	N/A			
Lights	X			
Sweeps	N/A			
Blade Type	Semi U			
Hyd. Tank	x			
Hoses	x			
Cutting Edge	x			
System one Under Crage	N/A			
C Frame	x			
Trunnions	x			
Hydraulic Cylinders	x			
Pins Bushings		x		
Steps	x			
Hand Rails	x			
Overall Condition	x			
Comments				

ENGINE	YES	NO	MISSING	OPERATIONAL
Blow By	x			
Turbo	x			
Radiator	x			
Oil Leaks		x		
Water Leaks		x		
Belts	x			
Emissions Label		x		
Exhaust	x			
Engine Type	Cat			
Engine Model	3306			
A/C Compessor		x		
Overall Condition	Good			
Comments				

DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL
Transmission	x	
Tracks	22''	
Sprockets	x	
Front Idler	x	
Rear Idler	x	
Bushings Turned	No	
Overall Condition	Good	
Comments		

LOGISTICS				
Length	19'			
Width	121''			
Height	10'			

MISC.				

EQUIFY
We Strengthen Your Business

EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.