

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20137	Caterpillar	D6D	1983	D4X06617

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	Closed				Frame	X			
Clean	X				Paint	X			
Seat	X				Sheet Metal	Minor Dents			
Seat Belts	X				Fiberglass	N/A			
Air Ride Seat	N/A				Mirrors	N/A			
Brake Type	X				Fuel Tanks	X			
Warning Lights	N/A				Bucket	N/A			
Guages	X				Wench	yes			
Mileage	N/A				Ripper	N/A			
Hours	3256				Screens	N/A			
Horn			Does Not Work		Lights	X			
Glass		Cracked			Sweeps	Yes			
Controls	X				Blade Type	Semi U			121"
Brakes	X				Hyd. Tank	x			
Door Controls	X				Hoses	x			
Heated Mirrors	N/A				Cutting Edge	x			
Lights	X				System one Under Crage	N/A			
Steering	Lever				C Frame	x			
Overall Condition	Good				Trunnions	x			
					Hydraulic Cylinders	x			
					Pins Bushings		x		
					Steps	x			
					Hand Rails	x			
					Overall Condition	x			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	x				Transmission	x			
Turbo	x				Tracks	22"			
Radiator	x				Sprockets	x			
Oil Leaks		x			Front Idler	x			
Water Leaks		x			Rear Idler	x			
Belts	x				Bushings Turned	No			
Emissions Label		x			Overall Condition	Good			
Exhaust	x								
Engine Type	Cat								
Engine Model	3306								
A/C Compressor		x							
Overall Condition	Good								
Comments					Comments				
LOGISTICS					MISC.				
Length	19'								
Width	121"								
Height	10'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.