EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20139	Caterpillar	D7	1978	92V05801

CAB	GOOD	FAIR	BAD	OPERATIONAL
Cab Type	CLOSED			
Clean	Yes			
Warning Lights	Operational			
Horn	Operational			
Glass	Some Damage			
AC	YES			
Heater	Yes			
Mileage	N/A			
Hours	2916			
Transmission Disconnect	N/A			
Dash Lights	N/A			
Gauges	Operational			
Lights	Operational			
Seat	Good			
Seat Belts	Operational			
Safety Lockout	Operational			
Hyd. Controls	Operational			
Back Up Camera	N/A			
Travel Alarm	Operational			
Park Brake	Operational			
Overall Condition	GOOD			
Comments				

EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Lights	Operational			
Tracks	Good			24''
Bushings	Good			
Sprocket	X			
Idlers	N/A			
Frame	Good			
Paint	Good			
Sheet Metal	Good			
Fiberglass	N/A			
Mirrors	Good			
Fuel Tanks	Good			
Lift Arms	Good			
Pins / Bushings	Good			
Ripper	3 shank			
Hyd Cylinders	Good			
Wench	N/A			
Screens	N/A			
Blade Type	Single Tilt Cylinder			138''
Sweeps	YES			
Overall Condition	GOOD			
Comments				

ENGINE	YES	NO	MISSING	OPERATIONAL
Blow By	Minor			
Turbo	X			
Radiator	X			
Oil Leaks		X		
Water Leaks		X		
Belts	Good			
Emissions Label	Yes			
Exhaust	Good			
Engine Type	Diesel			
Engine Model	3306			
Engine Make	CATERPILLAR			
Overall Condition	Good			
Comments				

DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL
Transmission	Yes	
Front Axle	N/A	
Rear Axle	N/A	
Rear Axle	N/A	
Transfer Case	N/A	
Overall Condition		
Comments		

LOGISTICS				
Length	22'			
Width	138''			
Height	11'			

MISC.				

EQUIFY
We Strengthen Your Business

EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.