

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20141	Case	550G	1985	JJG0255301

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	Closed				Frame	X			
Clean	X				Paint	X			
Seat	X				Sheet Metal	Minor Dents			
Seat Belts	X				Fiberglass	N/A			
Air Ride Seat	x				Mirrors	N/A			
Brake Type	X				Fuel Tanks	X			
Warning Lights	N/A				Bucket	N/A			
Guages	X				Front Scraffer	yes			
Mileage	N/A				Ripper	5 Shank			
Hours	15412				Push Block	Yes			
Horn			Does Not Work		Lights	X			
Glass	x				Blade Type	X			14'
Controls	X				Hyd. Tank	X			
Brakes	X				Hoses	X			
Door Controls	X				Cutting Edge	X			
A/C Heater	X				C Frame	X			
Lights	X				Trunnions	X			
Steering	GOOD				Hydraulic Cylinders	x			
Overall Condition	GOOD				Pins Bushings	x			
					Steps	x			
					Hand Rails	X			
					Circle Gear	x			
					Hyd Motors	x			
					Circle Pads		x		
					Overall Condition	Good			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	x				Transmission	x			
Turbo	x				Tires	14.00R24			
Radiator	x				Rims	x			
Oil Leaks		x			Lug Nuts Studs	x			
Water Leaks		x			Overall Condition	Good			
Belts	x								
Emissions Label		x							
Exhaust	x								
Engine Type	Cat								
Engine Model	3306								
A/C Compressor	YES	x							
Overall Condition	Good								
Comments					Comments				
LOGISTICS					MISC.				
Length	32'								
Width	13'								
Height	11'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.