EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20143	SAKAI	SV510D	1995	VSV11D-10132

CAB	GOOD	FAIR	BAD	OPERATIONAL
Cab Type	CLOSED			
Clean	X			
Seat	X			
Seat Belts	X			
Air Ride Seat	NO			
Brake Type	HYDRAULIC			
Warning Lights	X			
Guages	X			
Mileage	N/A			
Hours	5263			
Horn	NO			
Glass	CRACKED			
Controls	X			
Brakes	X			
Door Controls	X			
Lights	X			
Overall Condition	GOOD			
Comments				

EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Frame	X			
Paint	X			
Sheet Metal	X			
Fiberglass	X			
Mirrors	N/A			
Fuel Tanks	X			
Pins / Bushings	N/A			
Smooth Roller Front	84''			
Smooth Roller rear	N/A			
Front Padffoot	N/A			
Rear Padfoot	N/A			
Water System	N/A			
Drum Scraoers	X			
Rops	X			
Rubber Isalotors	X			
Pumps	X			
Lights	X			
Hyd. Hoses	X			
Duel Operator Stations	N/A			
Vibratory Motors Front	GOOD			
Vibratory Motors Rear	N/A			
Ballast Tank	N/A			
Rear Tires	X			23.1-26
Front Tires	N/A	GOOD		
Overall Condition				
Comments				

ENGINE	YES	NO	MISSING	OPERATIONAL
Blow By		X		
Turbo	X			
Radiator	X			
Oil Leaks		X		
Water Leaks		X		
Belts	X			
Emissions Label		X		
Exhaust	X			
Fuel Type	DIESEL			
Engine Model				
Engine Make	ISUZU			
Overall Condition	GOOD			
Comments				

DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL
Transmission	X	
Rear Axle	X	
Drive Motors	X	
Rims	X	
Lug Nuts	X	
Overall Condition	GOOD	
Comments		

LOGISTICS				
Length	19'			
Width	90''			
Height	9'			

MISC.				

EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.