EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER		
20148	Sterling	Dump Truck	2000	2FWYAZYBOYA914555		

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	DAY				Front Tires	х			11R22.5
Clean		х			Rear Tires	х			11R22.5
Seat		х			Rims	х			
Seat Belts	х				Lug Nuts	Х			
Air Ride Seat	YES				Wheel Base	Х			
Brake Type	AIR				Paint		х		
Warning Lights	х				Sheet Metal		Minor Dents		
Guages	х				Fiberglass		Cracks		
Mileage	592563				Mirrors	Х			
Hours	N/A				Fuel Tanks	Х			
Horn	х				Bed	DUMP			
Glass	х				Tailgate	х			
Cruise	х				Transfer Case	N/A			
Brakes	AIR				Air Ride Cab	N/A			
Engine Brake	х				Lights	x			
Sleeper Size	N/A				5Th Wheel	N/A			
Front Axle Weight	12,000				PTO	x			
Rear Axle Weight	40,000				Hyd. Tank	х			
GVWR	52,000				Tarp	MANUAL			
Sun Roof	N/A				Headace Rack	N/A			
Door Controls	x				Wet Kit	N/A			
Heated Mirrors	N/A				Frame	x			
Rear Sliding Glass	N/A				Overall Condition		х		
Overall Condition	.,,	х	İ	†				1	
			İ	†			1	1	
Comments		ı		·I	Comments				ı
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL		NON-OPERATIONAL	
Blow By	х				Transmission	Road Ranger 10 Speed			
Turbo	х				Front Axle	x			
Radiator	х				Middle Axle	x			
Oil Leaks		x			Rear Axle	x			
Water Leaks		x			Transfer Case	N/A			
Belts	х				Front Suspension	Spring			
Emissions Label		x			Rear Suspension	Air			
Exhaust	х				4 X 2	N/A			
Fuel Type	Diesel				4 X 4	N/A	N/A		
Engine Model	Series 60				4 X 6	x			
Engine Make	Detroit				Overall Condition	Good			
A/C Compessor	х								
Overall Condition	Good								
Comments					Comments				
LOGISTICS					MISC.	Good	Fair	Poor	
Length	27'								
Width	102''								
Height	10'								
						_			



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050

equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable, as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.