

**EQUIFY AUCTIONS INSPECTION REPORT**

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20151	Freuhauf	Flatbed	1999	FWT047901

BED	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Useable deck	40'								
Upper Deck	N/A								
Rear Deck	N/A								
Connections	GOOD								
Hitch	GOOD								
D Rings	N/A								
Tie Downs	GOOD								
Frame	GOOD								
Lights	GOOD								
Tank	N/A								
Baffles	N/A								
Jeep	N/A								
Stinger	N/A								
Paint		FAIR							
Metal	GOOD								
Hydraulics	N/A								
Dove Tail	N/A								
Ramps	N/A								
Suspension	SPRING								
Deck Condition	GOOD								
Head Ace Rack	N/A								
Tool Boxes	NN								
Fron Tires	GOOD			11R22.5					
Rear Tires	GOOD			11R22.5					
Rims / Lug Nuts	GOOD								
Overall Condition	GOOD								
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	N/A								
Turbo	N/A								
Radiator	N/A								
Oil Leaks	N/A								
Water Leaks	N/A								
Belts	N/A								
Emissions Label	N/A								
Exhaust	N/A								
Overall Condition	N								
Comments					Comments				
LOGISTICS					MISC.				
Length	40'								
Width	102"								
Height	5'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
[equifyauctions.com](http://equifyauctions.com)

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.