

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20671	Caterpillar	CP433C	2001	CATCP433L2JM01148

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	Good	FAIR	BAD	SIZE/CAPACITY
Cab Type	Open				Front Tires	N/A			
Clean	Yes				Rear Tires	Good			4.9-24
Warning Lights	N/A				Rims / Lugnuts	Good			
Horn	Yes				Drum	Padfoot			66"
Glass	N/A				Frame	Good			
AC	N/A				Paint	Good			
Heater	N/A				Sheet Metal	Good			
Mileage	N/A				Fiberglass	Good			
Hours	3444				Mirrors	N/A			
					Fuel Tanks	Good			
Dash Lights	N/A				Water System	N/A			
Gauges	Yes				Rubber Isolators	Good			
Lights	Yes				Rollers	N/A			
Seat	Yes				Pins / Bushings	Good			
Seat Belts	Yes				Lights	N/A			
Safety Lockout	N/A				Blade	N/A			
Hyd. Controls	Operational				Articulation	Good			
Travel Alarm	Operational				Drum Scrapers	Good			
Park Brake	Operational								
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	Minor				Transmission	X			
Turbo	Yes				Front Axle	N/A			
Radiator	Good				Rear Axle	X			
Oil Leaks	No				Rear Axle	OPERATIONAL			
Water Leaks	No				Transfer Case	N/A			
Belts	Good								
Emissions Label	No								
Exhaust	Good								
Engine Type	Diesel								
Engine Model	1935/2200								
Engine Make	Perkins								
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
LOGISTICS					MISC.				
Length	16'								
Width	72"								
Height	10'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. As this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.