

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20673	Chevrolet	C-7500	2006	1GBM7C1C06F410685

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab	Day				Dump Bed	Heil			
Clean	Operational				Front Tires	Good			11R24.5
Warning Lights	Operational				Rear Tires	Good			11R24.5
Horn	Yes				Rims / Lugnuts	Good			
Glass	Good				Wheel Base	151			
A/C Heater	Good				Frame	Good			
Mileage	243,459				Paint	Good			
Hours	N/A				Sheet Metal	Good			
PTO	Operational				Fiberglass	Good			
Dash Lights	Operational				Mirrors	Good			
Gauges	Operational				Fuel Tanks	Good			
Seat Belts	Operational				Lights	Operational			
Controls	Operational				Air Ride Cab	No			
Air Brakes	Operational				Transfer Case	N/A			
Sleeper Size	N/A				Steps	Good			
Front Axle Weight	12,000				Handrails	Good			
Rear Axle Weight	19,000				4 X 2	Yes			
GVWR	31,000				4 X 4	N/A			
Seat	Good				4 X 6	N/A			
Tilt	No				Wet Kit	N/A			
Telescope	No				Trailer Connections	Good			
Window Controls	Manual				Hitch	Pintal			
Power Locks	Manual				Pup Trailer	No			
Power Mirrors	No				Tail Gate	Operational			
Heated Mirrors	No				Tarp	Manual			
Overall Condition	Good				Overall Condition	GOOD			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	Minor				Transmission	Automatic			
Turbo	Yes				Front Axle	Good			
Radiator	Good				Rear Axle	N/A			
Oil Leaks		X			Rear Axle	Operational			
Water Leaks		X			Transfer Case	N/A			
Belts	Good				Front Suspension	Springs			
Emissions Label	Yes				Rear Suspension	Springs			
Exhaust	Good								
Engine Make	Caterpillar								
Engine Model	C-7								
Engine Type	Diesel								
Horse Power	n/a								
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
LOGISTICS					MISC.				
Length	26'				Travel Alarm	Good			
Width	102"				Park Brake	Good			
Height	10'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. As this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.