

**EQUIFY AUCTIONS INSPECTION REPORT**

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20773	Mustang	960		462342

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	OPEN				Tracks	N/A			
Clean	Yes				Tires / Lug Nuts	Good			10-16.5
Warning Lights	N/A				Sprockets	Good			
Horn	Inop				Idlers	Good			
Glass	Ok				Bushings	Good			
AC	N/A				Rubber Lugs	N/A			
Heater	N/A				Frame	Good			
Mileage	N/A				Paint	Good			
Hours	N/A				Sheet Metal	Good			
Transmission	N/A				Fiberglass	Good			
Dash Lights	Operational				Mirrors	N/A			
Gauges	Operational				Fuel Tanks	Good			
Lights	Operational				Bucket	No			
Seat	Ok				Lights	No			
Seat Belts	Operational				Hyd. Tank	Good			
Safety Lockout	Operational				Hoses	Good			
Hyd. Controls	Operational				Cutting Edge	N/A			
Door Condition	N/A				Aug. Hydraulics	N/A			
Travel Alarm	N/A				Coupler	Manual			
Park Brake	Inop								
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	Minor				Drive Motors	Yes			
Turbo	Yes								
Radiator	Good								
Oil Leaks	No								
Water Leaks	No								
Belts	Good								
Emissions Label	No								
Exhaust	Good								
Engine Type	Diesel								
Engine Model	4 Cylinder								
Engine Make	Isuzu								
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
LOGISTICS					MISC.				
Length	13'								
Width	68"								
Height	7'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.