

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20776	International	8600	2007	1HSHXHRX7J525358

Cab	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab	Day			48"	Dump Bed	N/A			
Clean	Operational				Front Tires	Good			11R22.5
Warning Lights	Operational				Rear Tires	Good			11R22.5
Horn	Yes				Rims / Lug Nuts	Good			
Glass	Good				Wheel Base	Good			
A/C Heater	Operational				Frame	Good			
Mileage	875,209				Paint	Good			
Hours	748,471				Sheet Metal	Good			
PTO	N/A				Fiberglass	Good			
Dash Lights	Operational				Mirrors	Good			
Gauges	Operational				Fuel Tanks	Good			
Seat Belts	Operational				Lights	Operational			
Controls	Operational				Air Ride Cab	Yes			
Air Brakes	Operational				Transfer Case	N/A			
Sleeper Size	N/A				Steps	Good			
Front Axle Weight	12,000				Handrails	Good			
Rear Axle Weight	40,000				4 X 2	N/A			
GVWR	52,000				4 X 4	N/A			
Seat	Good				4 X 6	Yes			
Tilt	Yes				Wet Kit	N/A			
Telescope	No				Trailer Connections	N/A			
Window Controls	Manual				Hitch	N/A			
Power Locks	Manual				Pup Trailer	N/A			
Power Mirrors	Manual				Tail Gate	N/A			
Heated Mirrors	Yes				Tarp	N/A			
Overall Condition					Overall Condition	GOOD			
Comments	170" Wheel Base				Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	Minor				Transmission	Automatic			
Turbo	Yes				Front Axle	Good			
Radiator	Good				Rear Axle	N/A			
Oil Leaks		X			Rear Axle	Operational			
Water Leaks		X			Transfer Case	N/A			
Belts	Good				Front Suspension	Springs			
Emissions Label	Yes				Rear Suspension	Air			
Exhaust	Good								
Engine Make	Cummins								
Engine Model	6 Cylinder								
Engine Type	Diesel								
Horse Power									
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
LOGISTICS					MISC.				
Length	24'				Back Up Alarm				
Width	102"				Park Brake				
Height	13'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. As this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.