

EQUIFY AUCTIONS INSPECTION REPORT

| ITEM NUMBER | MAKE | MODEL | YEAR | SERIAL NUMBER |
|-------------|----------|-------|------|-------------------|
| 20779 | Sterling | | 2005 | 2FWBA2DL56AV76430 |

| Cab | GOOD | FAIR | BAD | OPERATIONAL | EXTERIOR | GOOD | FAIR | BAD | SIZE/CAPACITY |
|-------------------|-----------------|------|---------|-------------|---------------------|----------------------|-----------------|-----|---------------|
| Cab | Day | | | | Dump Bed | U Shape | | | |
| Clean | Operational | | | | Front Tires | Good | | | 11R24.5 |
| Warning Lights | Operational | | | | Rear Tires | Good | | | 11R24.5 |
| Horn | Yes | | | | Rims / Lug Nuts | Good | | | |
| Glass | Good | | | | Wheel Base | Good | | | |
| A/C Heater | Operational | | | | Frame | Good | | | |
| Mileage | 476,915 | | | | Paint | Good | | | |
| Hours | N/A | | | | Sheet Metal | Good | | | |
| PTO | N/A | | | | Fiberglass | Good | | | |
| Dash Lights | Operational | | | | Mirrors | Good | | | |
| Gauges | Operational | | | | Fuel Tanks | Good | | | |
| Seat Belts | Operational | | | | Lights | Operational | | | |
| Controls | Operational | | | | Air Ride Cab | Yes | | | |
| Air Brakes | Operational | | | | Transfer Case | N/A | | | |
| Sleeper Size | N/A | | | | Steps | Good | | | |
| Front Axle Weight | 12,000 | | | | Handrails | Good | | | |
| Rear Axle Weight | 21,000 | | | | 4 X 2 | N/A | | | |
| GVWR | 33,000 | | | | 4 X 4 | N/A | | | |
| Seat | Good | | | | 4 X 6 | Yes | | | |
| Tilt | No | | | | Wet Kit | N/A | | | |
| Telescope | No | | | | Trailer Connections | N/A | | | |
| Window Controls | Manual | | | | Hitch | N/A | | | |
| Power Locks | Manual | | | | Pup Trailer | N/A | | | |
| Power Mirrors | No | | | | Tail Gate | N/A | | | |
| Heated Mirrors | No | | | | Tarp | N/A | | | |
| Overall Condition | | | | | Overall Condition | GOOD | | | |
| Comments | 150" Wheel Base | | | | Comments | | | | |
| ENGINE | YES | NO | MISSING | OPERATIONAL | DRIVE TRAIN | OPERATIONAL | NON-OPERATIONAL | | |
| Blow By | Minor | | | | Transmission | Operational 10 Speed | | | |
| Turbo | Yes | | | | Front Axle | Good | | | |
| Radiator | Good | | | | Rear Axle | Operational | | | |
| Oil Leaks | | X | | | Rear Axle | Operational | | | |
| Water Leaks | | X | | | Transfer Case | N/A | | | |
| Belts | Good | | | | Front Suspension | Springs | | | |
| Emissions Label | Yes | | | | Rear Suspension | Air | | | |
| Exhaust | Good | | | | | | | | |
| Engine Make | Caterpillar | | | | | | | | |
| Engine Model | C-11 | | | | | | | | |
| Engine Type | Diesel | | | | | | | | |
| Horse Power | | | | | | | | | |
| Overall Condition | Good | | | | Overall Condition | Good | | | |
| Comments | | | | | Comments | | | | |
| LOGISTICS | | | | | | | | | |
| Length | 26' | | | | MISC. | | | | |
| Width | 102" | | | | Back Up Alarm | | | | |
| Height | 10' | | | | Park Brake | | | | |
| | | | | | | | | | |
| | | | | | | | | | |



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.