

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20782	Caterpillar	325B	2001	2JR03483

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	FAIR	BAD	SIZE/CAPACITY
Cab Type	Closed				Front Tires	N/A		
Clean	No				Rear Tires	N/A		
Warning Lights	Operational				Rims / Lugnuts	N/A		
Horn	No				Swing Tower	Good		
Glass	Broken				Frame	Good		
AC	Does Not Work				Paint	Good		
Heater	Yes				Sheet Metal	Some Dents		
Mileage	N/A				Fiberglass	Some Damage		
Hours	16,130				Mirrors	No		
Transmission	N/A				Fuel Tanks	Good		
Dash Lights	Operational				Stick	10' 6"		
Gauges	Operational				Boom	Good		
Lights	Operational				Rollers	Good		
Seat	Yes				Idlers	Good		
Seat Belts	Yes				Tracks	Good		31.50"
Safety Lockout	Yes				Pins / Bushings	Good		
Hyd. Controls	Operational				Sprockets	Good		
Travel Alarm	No				Bushings	Good		
Park Brake	Yes				Turntable Motor	Good		
					Frame	Good		
					Lights	Good		
					Front Bucket	Good		51.50"
					Coupler	N/A		
					Blade	N/A		
					Center Swivel	Good		
Overall Condition		Fair			Overall Condition	Good		
Comments					Comments			
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL	
Blow By	Minor				Transmission	Yes		
Turbo	Yes				Front Axle	N/A		
Radiator	Good				Rear Axle	N/A		
Oil Leaks	No				Rear Axle	N/A		
Water Leaks	No				Transfer Case	N/A		
Belts	Good							
Emissions Label	No							
Exhaust	Good							
Engine Type	Diesel							
Engine Model	6 Cylinder							
Engine Make	Caterpillar							
Overall Condition	Good				Overall Condition	Good		
Comments					Comments			
LOGISTICS					MISC.			
Length	33'				Swing Motor	Good		
Width	132"							
Height	12'							



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.