

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20783	John Deere	410E	1997	TO410EX834020

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	Closed				Lights	Operational			
Clean	NO				Front Tires	Good			14.5/75-16.1
Warning Lights	Operational				Rear Tires	Good			21L-24
Horn			Inoperational		Rims / Lug Nuts	Good			
Glass	Broken				Atriculating Pins	Good			
AC	N/A				Frame	Good			
Heater	Operational				Paint	Good			
Mileage	N/A				Sheet Metal		Fair		
Hours	7350				Fiberglass	Good			
Transmission Disconnect	Operational				Mirrors	Good			
Dash Lights	Operational				Fuel Tanks	Good			
Gauges	Operational				Lift Arms	Good			
Lights	Operational				Pins / Bushings	Good			
Seat		Seat Cover Bad			Coupler	N/A			
Seat Belts	Operational				Hyd Cylinders	Good			
Safety Lockout	N/A				4 X 2	Yes			
Hyd. Controls	Operational				4 X 4	N/A			
Back Up Camera	N/A				Front Bucket	Fair			106"
Loader Scales	N/A				Boom Tower	N/A			
Travel Alarm	N/A				Rear Bucket	Good			24"
Park Brake			Does Not Work						
Overall Condition	Fair				Overall Condition	Good			
Comments	Glass is Broken				Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	Minor				Transmission	Yes			
Turbo	X				Front Axle	n/a			
Radiator	X				Rear Axle	Good			
Oil Leaks		X			Rear Axle	N/A			
Water Leaks		X			Transfer Case	N/A			
Belts	Good								
Emissions Label	Yes								
Exhaust	Good								
Engine Type	Diesel								
Engine Model	6 Cylinder								
Engine Make	John Deere								
Overall Condition	Good				Overall Condition	Good			
Comments					Comments				
LOGISTICS					MISC.				
Length	24'								
Width	96"								
Height	10'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.