

## EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
65472	Mack	CV713	2006	1M2AG11C57M056920

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab	Good				Tank	Good			
Clean	Operational				Front Tires	Good			11R24.5
Warning Lights	Operational				Rear Tires	Good			11R22.5
Horn	Yes				Rims / Lug Nuts	Good			
Glass	Good				Wheel Base	259"			
A/C Heater	Operational				Frame	Good			
Mileage	173,161				Paint	Good			
Hours	14,228				Sheet Metal	Good			
PTO	Operational				Fiberglass	Good			
Dash Lights	Operational				Mirrors	Good			
Gauges	Operational				Fuel Tanks	Good			
Seat Belts	Operational				Bed	Good			
Controls	Operational				Tailgate	N/A			
Air Brakes	Operational				Transfer Case	N/A			
Sleeper Size	N/A				Air Ride Cab	Yes			
Front Axle Weight	N/A				Lights	Operational			
Rear Axle Weight	N/A				4 X 2	N/A			
GVWR	N/A				4 X 4	N/A			
Seat	Good				4 X 6	Yes			
Tilt	Yes				Product Tanks	Good			
Telescope	N/A				Hose Reels	Good			
Window Controls	Manual				Rear Door	N/A			
Power Locks	Manual				Front Reel	N/A			
Power Mirrors	No				Vac Hose	Good			
Heated Mirrors	No								
Overall Condition	Good				Overall Condition	GOOD			
Comments					Comments	National Vacuum Pump, / Double Frame.			
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	Minor				Transmission	Operational 10 Speed			
Turbo	Yes				Front Axle	Good			
Radiator	Good				Rear Axle	Operational			
Oil Leaks		X			Rear Axle	Operational			
Water Leaks		X			Transfer Case	N/A			
Belts	Good				Front Suspension	Springs			
Emissions Label	Yes				Rear Suspension	Camel Back			
Exhaust	Good								
Engine Make	N/A								
Engine Model	6 Cylinder								
Engine Type	Diesel								
Overall Condition	Good				Overall Condition	Good			
Comments					Comments	Unable to Run Pump.			
LOGISTICS					MISC.				
Length	32'								
Width	102"								
Height	13'								
					Park Brake	Good			



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING  
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050  
[equifyauctions.com](http://equifyauctions.com)

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. As this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.