

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
89041	CHEVROLET	2500	2009	1GCHK49K49E156888

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	EXTENDED				Front Tires	X			265/75R16
Clean	X				Rear Tires	X			265/75R16
Seat	X				Rims	X			
Seat Belts	X				Lug Nuts	X			
Air Ride Seat	N/A				Wheel Base	N/A			
Brake Type	HYDRAULIC				Paint	GOOD			
Warning Lights	Check Eng, Stays On				Sheet Metal	GOOD			
Guages	X				Fiberglass	GOOD			
Mileage	210970				Mirrors	GOOD			
Hours	N/A				Fuel Tanks	GOOD			
Horn	X				Bed	6'7"			
Glass	X				Tailgate	GOOD			
Cruise	YES				Transfer Case	X			
Brakes	GOOD				Air Ride Cab	N/A			
Engine Brake	N/A				Lights	OPERATIONAL			
Sleeper Size	N/A				5Th Wheel	N/A			
Front Axle Weight	4,200				PTO	N/A			
Rear Axle Weight	6,084				Hyd. Tank	N/A			
GVWR	9,200				Tarp	N/A			
Sun Roof	N/A				Headace Rack	N/A			
Door Controls	GOOD				Wet Kit	N/A			
Heated Mirrors	N/A				Frame	GOOD			
Rear Sliding Glass	N/A				Overall Condition	GOOD			
Tilt	X								
Overall Condition	GOOD								
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By		X			Transmission	X			
Turbo		X			Front Axle	X			
Radiator	X				Middle Axle	X			
Oil Leaks		X			Rear Axle	X			
Water Leaks		X			Transfer Case	X			
Belts	X				Front Suspension	SPRING			
Emissions Label	X				Rear Suspension	SPRING			
Exhaust	X				4 X 2	N/A			
Fuel Type	Gas				4 X 4	yes			
Engine Model	6.0L				4 X 6	N/A			
Engine Make	GM				Overall Condition	GOOD			
A/C Compressor	YES								
Overall Condition	GOOD				Comments				
Comments									
LOGISTICS					MISC.	Good	Fair	Poor	
Length	20'				Brushguard				
Width	102"				Hitch				
Height	7'7"				Power Locks,Windows, Mirrors				



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
 equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.