EQUIFY AUCTIONS INSPECTION REPORT									
ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER		1			
89044	CHEVROLET	2500	2013	1GC2KVCG4DZ138358					
CAB Column	GOOD EXTENDED	FAIR	BAD	OPERATIONAL	EXTERIOR Front Tires	GOOD	FAIR	BAD	SIZE/CAPACITY LT265/70R17
Cab Type Clean	EXTENDED				Rear Tires	x			LT265/70R17 LT265/70R17
Seat	×				Rims	x			L1205/70K17
Seat Belts	×					x			
Air Ride Seat	N/A				Lug Nuts Wheel Base	N/A			
Brake Type	HYDRAULIC				Paint	GOOD			
Warning Lights	V				Sheet Metal	GOOD			
Guages	×				Fiberglass	GOOD			
Mileage	138208				Mirrors	GOOD			
Hours	N/A				Fuel Tanks	GOOD			
	N/A				Bed	6'7''			
Horn	x					-			
Glass	YES			-	Tailgate	GOOD	-		
Cruise	GOOD				Transfer Case	~			
Brakes					Air Ride Cab	N/A OPERATIONAL			
Engine Brake	N/A				Lights	N/A			
Sleeper Size	N/A				5Th Wheel				
Front Axle Weight	4,400				PTO	N/A			
Rear Axle Weight	6,200				Hyd. Tank	N/A			
GVWR	9,500				Tarp	N/A			
Sun Roof	N/A GOOD				Headace Rack	N/A N/A			
Door Controls					Wet Kit	GOOD			
Heated Mirrors	N/A				Frame				
Rear Sliding Glass	N/A			-	Overall Condition	GOOD			
Tilt	X			-		-			
Overall Condition	GOOD			-		-			
	-			1		-			
Comments					Comments				
ENGINE	YES NO MISSING OPERATIONAL			DRIVE TRAIN	OPERATIONAL		NON-OPERATIONAL		
Blow By	TES	X	WIISSING	OPERATIONAL	Transmission	X		NON-OPERATIONAL	
Turbo		×			Front Axle	x			
Radiator	x	^			Middle Axle	x			
Oil Leaks	^	x			Rear Axle	x			
Water Leaks		×			Transfer Case	×			
Belts	v	^			Front Suspension	SPRING			
Emissions Label	×				Rear Suspension	SPRING			
Exhaust	×				4 X 2	N/A			
					4 X 2 4 X 4	YES			
Fuel Type Engine Model	DUEL 6.0L	1		+	4 X 4 4 X 6	N/A			
Engine Make	GM				0verall Condition	GOOD			
-	YES			DOES NOT WORK	Overall Condition	GOOD			
A/C Compessor	GOOD			DOES NOT WORK		-			
Overall Condition Comments	GOOD					-			
Juli intento				Comments					
LOGISTICS					MISC.	Good	Fair	Poor	
Length	20'				Brusg Guard				
Width	90"	1	1	1	Nurf Bars		1	1	
Height	6'			1	Power Locks, Windows, Mirrors		1		
	Ť			1		-	1		
	-			1		-	1		
		I	1	1			1	1	



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050

equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable, as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report. All this inspection was performed.